


**PENSWASTAAN PENYENGGARAAN
JALAN-JALAN PERSEKUTUAN DI SABAH
(PANTAI BARAT & PENDALAMAN)**



THE GOVERNMENT OF MALAYSIA

**LAPORAN KEMAJUAN BULANAN
No. 9**

MEI 2004



Jabatan Kerja Raya, Negeri Sabah

Kontraktor : Lintasan Resources Sdn. Bhd. 566483-H

R 02

**PENYENGGARAAN
BAHU JALAN
(SHOULDER)**

DISTRICT : PENAMPANG

ROUTE NO. : 501 JALAN KOTA KINABALU-PENAMPANG-LOK KAWI

LOCATION : (KM 7.400)LHS

R02 SHOULDER MAINTENANCE

Film Batch No. 0953/5



BEFORE

Film Batch No. 0953/6



AFTER

DISTRICT : PENAMPANG

ROUTE NO. : 501 JALAN KOTA KINABALU-PENAMPANG-LOK KAWI

LOCATION : (KM 7.500)LHS

R02 SHOULDER MAINTENANCE

Film Batch No. 0953/7



BEFORE

Film Batch No. 0953/13



AFTER

R02 SHOULDER MAINTENANCE

Film Batch No: 0570/1



BEFORE

Film Batch No: 0949/6



IN PROGRESS

Film Batch No: 0949/8



AFTER

DISTRICT : TAMBUNAN
ROUTE NO. : 500 JALAN KK-KGU-TENOM

LOCATION : CH51.000 (KM60.900)

R02: ROAD SHOULDER



FILM BATCH NO: 0435/1

BEFORE



FILM BATCH NO: 0435/3

IN PROGRESS



FILM BATCH NO: 0435/4

AFTER

LINTASAN RESOURCES SDN. BHD.
SHOULDER REPAIR
GRAND SUMMARY

MONTH: MAY 2004

R02 - SHOULDER REPAIR				
DISTRICT	ROUTE NO.	ROAD NAME	EARTH (m2)	GRAVEL (m2)
Kota Belud	01	Jalan Kota Kinabalu-Kudat		
Kota Marudu	01	Jalan Kota Kinabalu-Kudat		
Kudat	01	Jalan Kota Kinabalu-Kudat		
Tuaran	01	Jalan Kota Kinabalu-Kudat		
	22	Jalan Kota Kinabalu-Sandakan		
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat		
	01	Jalan Kota Kinabalu-Sindumin		
	606	Jalan Susur Sepangar Bay		
	607	Jalan Masuk Ke Pelabuhan Baru		
	608	Jalan K Masuk Ke Lapangan Terbang Lama		
Penampang	500	Jalan Kota Kinabalu-Keningau-Tenom		3,119.10
	501	Jalan Kota Kinabalu-Penampang-Lok Kawi		7,931.28
	01	Jalan Kota Kinabalu-Sindumin		
Papar	01	Jalan Kota Kinabalu-Sindumin		
Ranau	22	Jalan Kota Kinabalu-Sandakan	239.00	
Tambunam	500	Jalan Kota Kinabalu-Keningau-Tenom	12.00	
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom		57.50
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom		
Beaufort	01	Jalan Kota Kinabalu-Sindumin	2.50	30.83
	502	Jalan Beaufort-Menumbok		5.05
Kuala Penyu	502	Jalan Beaufort-Menumbok		
Sipitang	01	Jalan Kota Kinabalu-Sindumin		
TOTAL			253.50	11,143.76

LINTASAN RESOURCES SDN BHD
(566/483-II)
PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY

Ending Period : 31st May 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m ²)		GRAVEL SHOULDER AREA (m ²)	
				PREVIOUS MONTH	CURRENT MONTH	PREVIOUS MONTH	CURRENT MONTH
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat			20,569.25	-
2	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin			75.75	-
3	Penampang	501	Jalan KK - Penampang -Lok Kawi			188.85	7,931.28
4	Penampang	500	Jalan KK - Keningau -Tenom			834.22	3,119.10
5	Papar	01	Jalan Kota Kinabalu - Sindumin			207.27	-
6	Tuaran	01	Jalan Kota Kinabalu - Kudat			1,520.00	-
TOTAL						23,395.34	11,050.38
							34,445.72

LINTASAN RESOURCES SDN BHD (566483-H)

PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR RECORD

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m ²)	GRAVEL SHOULDER AREA (m ²)
	Ranau	22	Jalan Kota Kinabalu - Sandakan	239.00	-
TOTAL				239.00	-

Checked & Certified Correct By :

Checked & Certified Correct By :

For Lintasan Resources Sdn Bhd

For Jabatan Kerja Raya

LINTASAN RESOURCES SDN BHD (566/485-II)
PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR RECORD

Ending Period : 31st May 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	AREA (m ²) - Earth Shoulder			AREA (m ²) - Gravel Shoulder		
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	27.00	0.00	27.00	90.07	0.00	90.07
2	Beaufort	502	Jalan Beaufort-Menumbok	175.00	0.00	175.00	54.72	5.05	59.77
3	Sipitang	01	Jalan Kota Kinabalu - Sindumin	0.00	0.00	0.00	33.85	0.00	33.85
4	Kuala Penyu	502	Jalan Beaufort-Menumbok	0.00	0.00	0.00	119.70	0.00	119.70
TOTAL				202.00	-	202.00	298.34	5.05	303.39