

# RO2

PENYENGGARAAN BAHU  
JALAN

(SHOULDER)

DISTRICT : PENAMPANG  
ROUTE NO : 500 JALAN KENINGAU-TENOM  
LOCATION : CH43.400 (RHS)

## R02 SHOULDER REPAIR



BEFORE



IN PROGRESS



AFTER

DISTRICT : BEAUFORT  
ROUTE NO : 01 JALAN KOTA KINABALU -SINDUM IN  
LOCATION : CH 84.190 -84.250 (KM 85.950 -86.010) -RHS

## R02 SHOULDER REPAIR



**BEFORE**



**IN PROGRESS**



**AFTER**

LINTASAN RESOURCES SDN BHD  
PRIVATISATION OF LABUAN FEDERAL ROADS MAINTENANCE

---

**R02 ~ ROAD SHOULDER.**

**Road Name : Jalan Patau-patau**

Route No : L731

Location : KM 3.60 (RHS)

Date : 15/10/2007

**BEFORE**



Film Batch: LJ07-05-157

**IN PROGRESS**



Film Batch: LJ07-05-192

**AFTER**



Film Batch: LJ07-14-147

LINTASAN RESOURCES SDN. BHD.  
**SHOULDER REPAIR**  
**GRAND SUMMARY**

MONTH:   OCTOBER 2007  

DISTRICT	ROUTE NO	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
			Previous	Current	Cumm.	Previous		Current		Cumm.	
			Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Vol (m <sup>3</sup> )	Area (m <sup>2</sup> )	Vol (m <sup>3</sup> )	Area (m <sup>2</sup> )	Vol (m <sup>3</sup> )
Kota Belud	01	Jalan Kota Kinabalu-Kudat	8,236.05	0.00	8,236.05	360.00	36.00	0.00	0.00	360.00	36.00
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	1,437.00	0.00	1,437.00	0.00	0.00	0.00	0.00	0.00	0.00
Kudat	01	Jalan Kota Kinabalu-Kudat	7,850.50	0.00	7,850.50	0.00	0.00	0.00	0.00	0.00	0.00
Tuaran	01	Jalan Kota Kinabalu-Kudat	13,702.14	0.00	13,702.14	11,133.70	1,669.02	0.00	0.00	11,133.70	1,669.02
	22	Jalan Kota Kinabalu-Sandakan	23,943.32	0.00	23,943.32	8,661.90	1,394.16	0.00	0.00	8,661.90	1,394.16
	503	Jalan Berungis-Kota Belud	1,984.53	0.00	1,984.53	26,512.07	3,976.81	0.00	0.00	26,512.07	3,976.81
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	1,679.96	0.00	1,679.96	768.56	175.24	0.00	0.00	768.56	175.24
	01	Jalan Kota Kinabalu-Sindumin	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	606	Jalan Susur Sepangar Bay	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	607	Jalan Masuk Ke Pelabuhan Baru	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	608	Jalan Masuk ke Lapangan Terbang Lama	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Penampang	01	Jalan Kota Kinabalu-Sindumin	0.00	0.00	0.00	277.24	41.65	0.00	0.00	277.24	41.65
	500	Jalan Kota Kinabalu-Keningau-Tenom	15,163.43	12.15	15,175.58	30.00	7.50	19,534.45	1,563.83	19,564.45	1,571.33
	501	Jalan Kota Kinabalu-Penampang-Lokkawi	7,372.00	0.00	7,372.00	5.76	5.36	0.00	0.00	5.76	5.36
Papar	01	Jalan Kota Kinabalu-Sindumin	6,388.00	634.01	7,022.01	8,730.33	670.31	0.00	0.00	8,730.33	670.31
Ranau	22	Jalan Kota Kinabalu-Sandakan	24,460.45	594.50	25,054.95	3,398.06	450.94	0.00	0.00	3,398.06	450.94
Tambunan	500	Jalan Kota Kinabalu-Keningau-Tenom	21,742.30	0.00	21,742.30	1,671.26	189.29	0.00	0.00	1,671.26	189.29
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	2,220.00	0.00	2,220.00	374.40	36.20	0.00	0.00	374.40	36.20
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	480.00	0.00	480.00	0.00	0.00	0.00	0.00	0.00	0.00
Beaufort	01	Jalan Kota Kinabalu-Sindumin	7,300.90	652.50	7,953.40	8,271.00	857.73	0.00	0.00	8,271.00	857.73
	502	Jalan Beaufort-Menumbok	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Sipitang	01	Jalan Kota Kinabalu-Sindumin	0.00	0.00	0.00	3,474.50	602.48	0.00	0.00	3,474.50	602.48
Kuala Penyu	502	Jalan Beaufort-Menumbok	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
<b>TOTAL</b>			143,960.58	1,893.16	145,853.74	73,668.78	10,112.69	19,534.45	1,563.83	93,203.23	11,676.52

**LINTASAN RESOURCES SDN. BHD.**

PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

MONTH: OCTOBER 2007

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	8,236.05	-	8,236.05	360.00	36.00			360.00	36.00
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	1,437.00	-	1,437.00	-	-	-	-	-	-
3	Kudat	01	Jalan Kota Kinabalu - Kudat	7,850.50	-	7,850.50	-	-	-	-	-	-
<b>TOTAL</b>				<b>17,523.55</b>	<b>-</b>	<b>17,523.55</b>	<b>360.00</b>	<b>36.00</b>	<b>-</b>	<b>-</b>	<b>360.00</b>	<b>36.00</b>

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KOTA BELUD  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU- KUDAT  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS	
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume		
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)		
<b>BROUGHT FORWARD:</b>				-	-	-	8,236.05	-	-	-	360.00	36.00		
1														
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
<b>BALANCE END OF OCT :</b>							8,236.05				360.00	36.00		

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KOTA MARUDU  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	1,437.00	-	-	-			
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>BALANCE END OF OCT:</b>							1,437.00				0.00	0.00	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KUDAT  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
<b>BROUGHT FORWARD:</b>				-	-	-	7,850.50	-	-	-			
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>BALANCE END OF OCT :</b>							7,850.50				0.00	0.00	

**LINTASAN RESOURCES SDN. BHD.**

PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

Month: October 2007

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	1,679.96	-	1,679.96	768.56	175.24	-	-	768.56	175.24
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	13,702.14	-	13,702.14	11,133.70	1,669.02	-	-	11,133.70	1,669.02
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	23,943.32	-	23,943.32	8,661.90	1,394.16	-	-	8,661.90	1,394.16
4	Tuaran	503	Jalan Berungis - Kota Belud	1,984.53	-	1,984.53	26,512.07	3,976.81	-	-	26,512.07	3,976.81
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	-	-	-	-	-	-	-	-	-
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	-	-	-	-	-	-	-	-	-
<b>TOTAL</b>				<b>41,309.95</b>	<b>-</b>	<b>41,309.95</b>	<b>47,076.23</b>	<b>7,215.23</b>	<b>-</b>	<b>-</b>	<b>47,076.23</b>	<b>7,215.23</b>

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** TUARAN  
**ROUTE NO.** 503  
**ROAD NAME:** JALAN BERUNGIS - KOTA BELUD  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
		<b>BROUGHT FORWARD:</b>		-	-	-	1,984.53	-	-	-	26,512.07	3,976.81	
<b>TOTAL :</b>							1,984.53				26,512.07	3,976.81	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KOTA KINABALU  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
		<b>BROUGHT FORWARD:</b>		-	-	-	1,679.96	-	-	-	768.56	175.24	
<b>TOTAL:</b>							1,679.96				768.56	175.24	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** TUARAN  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
		<b>BROUGHT FORWARD:</b>		-	-	-	13,702.14	-	-	-	11,133.70	1,669.02	
<b>TOTAL:</b>							13,702.14				11,133.70	1,669.02	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** TUARAN  
**ROUTE NO.** 22  
**ROAD NAME:** JALAN KOTA KINABALU - SANDAKAN  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
BROUGHT FORWARD:				-	-	-	23,943.32	-	-	-	8,661.90	1,394.16	
<b>TOTAL :</b>							23,943.32				8,661.90	1,394.16	

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

***SUMMARY- SHOULDER REPAIR RECORD***

*Month : October 2007*

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Ranau	22	Jalan Kota Kinabalu - Sandakan	24,460.45	594.50	25,054.95	3,398.06	450.94	-	-	3,398.06	450.94
			<b>TOTAL</b>	<b>24,460.45</b>	<b>594.50</b>	<b>25,054.95</b>	<b>3,398.06</b>	<b>450.94</b>	<b>-</b>	<b>-</b>	<b>3,398.06</b>	<b>450.94</b>

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** Ranau  
**ROUTE NO.** 22  
**ROAD NAME:** Jalan Kota Kinabalu - Sandakan  
**MONTH:** October 2007

ITEM	DATE		CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
			From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
					(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD FROM SEPTEMBER 2007:</b>							<b>24,460.45</b>				<b>3,398.06</b>	<b>450.94</b>		
1	18/10/2007	113.20	76.600	76.660	60.00	2.00		120.00						RHS
2	19/10/2007	113.80	77.200	77.235	35.00	1.50		52.50						RHS
3	23/10/2007	114.40	77.800	77.850	50.00	2.00		100.00						RHS
4	26/10/2007	114.90	78.300	78.345	45.00	2.00		90.00						RHS
5	29/10/2007	115.30	78.700	78.740	40.00	1.80		72.00						RHS
6	30/10/2007	115.90	79.300	79.380	80.00	2.00		160.00						RHS
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
<b>CARRIED FORWARD:</b>								<b>25,054.95</b>				<b>3,398.06</b>	<b>450.94</b>	

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

Month : OCTOBER 2007

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	7,300.90	652.50	7,953.40	8,271.00	857.73	-	-	8,271.00	857.73
2	Beaufort	502	Jalan Beaufort - Menumbok	-	-	-	-	-	-	-	-	-
3	Sipitang	01	Jalan Kota Kinabalu - Sindumin	-	-	-	3,474.50	602.48	-	-	3,474.50	602.48
4	Kuala Penyu	502	Jalan Beaufort - Menumbok	-	-	-	-	-	-	-	-	-
<b>TOTAL</b>				<b>7,300.90</b>	<b>652.50</b>	<b>7,953.40</b>	<b>11,745.50</b>	<b>1,460.21</b>	<b>-</b>	<b>-</b>	<b>11,745.50</b>	<b>1,460.21</b>

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** BEAUFORT  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - SINDUMIN  
**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	<b>7,300.90</b>	-	-	-	<b>8271.00</b>	<b>857.73</b>	-
1	24/10/2007	83.975	84.040	65.00	2.00	0.200	130.00						LHS
2	24/10/2007	84.190	84.250	60.00	2.00	0.200	120.00						LHS
3	24/10/2007	84.545	84.630	85.00	2.50	0.200	212.50						LHS
4	24/10/2007	84.575	84.615	40.00	2.50	0.200	100.00						RHS
5	24/10/2007	84.840	84.885	45.00	2.00	0.200	90.00						LHS
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>CARRIED FORWARD:</b>							<b>7,953.40</b>				<b>8,271.00</b>	<b>857.73</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** SIPITANG

**ROUTE NO.** 01

**ROAD NAME:** JALAN KOTA KINABALU - SINDUMIN

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	0.00	-	-	-	3,474.50	602.48	-
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>CARRIED FORWARD:</b>							0.00				3,474.50	602.48	

**LINTASAN RESOURCES SDN. BHD.**

PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY - SHOULDER REPAIR RECORD**

Month : OCTOBER 2007

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	TAMBUNAN	500	Jalan Kota Kinabalu - Keningau - Tenom	21,742.30	-	21,742.30	1,671.26	189.29	-	-	1,671.26	189.29
2	KENINGAU	500	Jalan Kota Kinabalu - Keningau - Tenom	2,220.00	-	2,220.00	374.40	36.20	-	-	374.40	36.20
3	TENOM	500	Jalan Kota Kinabalu - Keningau - Tenom	480.00	-	480.00	-	-	-	-	-	-
<b>TOTAL</b>				<b>24,442.30</b>	<b>-</b>	<b>24,442.30</b>	<b>2,045.66</b>	<b>225.49</b>	<b>-</b>	<b>-</b>	<b>2,045.66</b>	<b>225.49</b>

LINTASAN RESOURCES SDN. BHD.  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

**R02 SHOULDER REPAIR RECORD**

DISTRICT: TAMBUNAN  
 ROUTE NO. 500  
 ROAD NAME: JLN K. KINABALU - KENINGAU - TENOM  
 MONTH: October 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>							21,742.30				1,671.26	189.29	
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>TOTAL</b>							21,742.30				1,671.26	189.29	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KENINGAU  
**ROUTE NO.** 500  
**ROAD NAME:** JLN K. KINABALU - KENINGAU - TENOM  
**MONTH:** October 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
<b>BROUGHT FORWARD:</b>							2,220.00				374.40	36.20	
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>TOTAL</b>							2,220.00				374.40	36.20	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** TENOM

**ROUTE NO.** 500

**ROAD NAME:** JLN K. KINABALU - KENINGAU - TENOM

**MONTH:** October 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>							480.00				0.00	0.00	
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>TOTAL</b>							480.00				0.00	0.00	

**LINTASAN RESOURCES SDN. BHD.**  
PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

Month: OCTOBER 2007

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	-	-	-	277.24	41.65	-	-	277.24	41.65
3	Papar	01	Jalan Kota Kinabalu - Sindumin	6,388.50	634.01	7,022.51	8,730.33	670.31	-	-	8,730.33	670.31
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	15,163.43	12.15	15,175.58	30.00	7.50	19,534.45	1,563.83	19,564.45	1,571.33
5	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	7,372.00	-	7,372.00	5.76	5.36	-	-	5.76	5.36
6	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	-	-	-	-	-	-	-	-	-
<b>TOTAL</b>				<b>28,923.93</b>	<b>646.16</b>	<b>29,570.09</b>	<b>9,043.33</b>	<b>724.82</b>	<b>19,534.45</b>	<b>1,563.83</b>	<b>28,577.78</b>	<b>2,288.65</b>

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 01

**ROAD NAME:** JALAN KK-SINDUMIN

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
							0.00				277.24	41.65	
<b>TOTAL:</b>							0.00				277.24	41.65	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PAPAR

**ROUTE NO.:** 01

**ROAD NAME:** JALAN KK-SINDUMIN

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m <sup>2</sup> )	Length (m)	Width (m)	Depth (m)	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>							<b>6,388.50</b>				<b>8,730.33</b>	<b>670.31</b>	
1	05/10/07	44.735	44.756	21	0.80		16.80						RHS
2	05/10/07	44.460	44.509	49	1.40		68.60						RHS
3	05/10/07	44.719	44.727	8	1.70		14.11						RHS
4	06/10/07	44.356	44.376	20	1.90		38.00						LHS
5	06/10/07	43.166	43.183	17	2.00		34.00						LHS
6	08/10/07	43.385	43.425	40	1.00		40.00						RHS
7	09/10/07	34.365	34.395	30	1.00		30.00						LHS
8	09/10/07	34.455	34.495	40	1.00		40.00						RHS
9	10/10/07	34.435	34.465	30	1.00		30.00						LHS
10	10/10/07	34.545	34.565	20	1.00		20.00						LHS
11	10/10/07	34.546	34.566	20	2.50		50.00						RHS
12	10/10/07	34.635	34.655	20	1.00		20.00						LHS
13	11/10/07	34.835	34.885	50	1.50		75.00						RHS
14	11/10/07	34.885	34.905	20	1.00		20.00						LHS
15	11/10/07	35.035	35.070	35	3.50		122.50						RHS
16	11/10/07	38.335	38.350	15	1.00		15.00						RHS
<b>TOTAL:</b>							<b>7,022.51</b>				<b>8,730.33</b>	<b>670.31</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 500

**ROAD NAME:** JLN KK-KENINGAU-TENOM

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
<b>BROUGHT FORWARD:</b>							<b>15,163.43</b>				<b>30.00</b>	<b>7.50</b>	
1	02/10/07	43.400	43.500					100	3.00	0.150	300.00	45.00	RHS
2	04/10/07	31.800	31.500	3.00	1.50		4.50				0.00	0.00	LHS
3	04/10/07	32.400	41.900	3.00	1.50		4.50				0.00	0.00	LHS
4	06/10/07	24.100	24.220	1.20	2.00		2.40				0.00	0.00	LHS
5	06/10/07	31.400	31.350	0.50	1.50		0.75				0.00	0.00	LHS
6	10/10/07	38.200	38.301					101	2.55	0.110	257.55	28.33	RHS
7	10/10/07	38.305	38.386					81	1.60	0.080	129.60	10.37	RHS
8	10/10/07	38.285	38.374					89	1.50	0.090	133.50	12.02	LHS
9	10/10/07	38.500	38.538					38	1.00	0.080	38.00	3.04	LHS
10	10/10/07	38.450	38.519					69	1.20	0.080	82.80	6.62	RHS
11	10/10/07	38.519	38.590					71	3.00	0.110	213.00	23.43	RHS
12	10/10/07	38.590	38.658					68	1.55	0.080	105.40	8.43	RHS
13	11/10/07	38.650	38.760					110	1.35	0.080	148.50	11.88	RHS
14	11/10/07	38.760	38.805					45	1.15	0.080	51.75	4.14	LHS
15	11/10/07	38.806	38.866					60	1.25	0.080	75.00	6.00	RHS
16	11/10/07	38.870	39.163					293	1.45	0.100	424.85	42.49	RHS
17	11/10/07	39.020	39.030					10	1.05	0.080	10.50	0.84	LHS
18	11/10/07	42.900	43.010					110	1.50	0.130	165.00	21.45	LHS
19	11/10/07	42.900	42.990					90	1.50	0.130	135.00	17.55	RHS
20	16/10/07	5.014	5.282					268	3.00	0.080	804.00	64.32	LHS
21	16/10/07	5.050	5.177					127	3.00	0.050	381.00	19.05	RHS
22	16/10/07	5.890	5.951					61	3.50	0.100	213.50	21.35	LHS
23	16/10/07	5.955	6.021					66	2.80	0.110	184.80	20.33	RHS
24	16/10/07	6.050	6.125					75	3.50	0.120	262.50	31.50	RHS
25	16/10/07	6.052	6.138					86	2.50	0.120	215.00	25.80	LHS
26	16/10/07	6.090	6.194					104	1.50	0.080	156.00	12.48	RHS
27	17/10/07	6.530	6.657					126.8	2.00	0.050	253.60	12.68	LHS
28	17/10/07	6.850	7.019					169	2.50	0.080	422.50	33.80	RHS
29	17/10/07	6.990	7.104					114	2.00	0.080	228.00	18.24	LHS
30	17/10/07	7.145	7.331					186	2.00	0.050	372.00	18.60	RHS
<b>CARRIED FORWARD:</b>							<b>15,175.58</b>				<b>5,793.35</b>	<b>527.23</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 500

**ROAD NAME:** JLN KK-KENINGAU-TENOM

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
<b>BROUGHT FORWARD:</b>							15,175.58				5,793.35	527.23	
31	17/10/07	7.810	7.910					100	1.20	0.080	120.00	9.60	RHS
32	17/10/07	7.800	7.900					100	2.20	0.080	220.00	17.60	RHS
33	17/10/07	8.066	8.141					75	2.00	0.050	150.00	7.50	RHS
34	17/10/07	8.200	8.345					145	2.20	0.080	319.00	25.52	LHS
35	17/10/07	8.300	8.567					267	3.00	0.080	801.00	64.08	RHS
36	18/10/07	9.400	9.485					85	3.00	0.090	255.00	22.95	RHS
37	18/10/07	9.780	9.835					55	2.60	0.120	143.00	17.16	LHS
38	18/10/07	9.780	9.835					55	2.60	0.110	143.00	15.73	RHS
39	18/10/07	9.900	10.100					200	3.00	0.080	600.00	48.00	RHS
40	18/10/07	10.200	10.280					80	2.20	0.080	176.00	14.08	RHS
41	18/10/07	10.200	10.300					100	3.00	0.080	300.00	24.00	LHS
42	18/10/07	10.600	10.700					100	3.00	0.050	300.00	15.00	RHS
43	18/10/07	10.700	10.800					100	3.00	0.050	300.00	15.00	RHS
44	19/10/07	11.008	11.035					27	1.00	0.075	27.00	2.03	LHS
45	19/10/07	11.029	11.069					40	1.00	0.083	40.00	3.32	RHS
46	19/10/07	11.136	11.225					89	1.30	0.083	115.70	9.60	LHS
47	19/10/07	11.210	11.213					21	1.20	0.083	25.20	2.09	RHS
48	19/10/07	11.242	11.326					84	1.00	0.075	84.00	6.30	LHS
49	19/10/07	11.476	11.547					71	1.60	0.083	113.60	9.43	RHS
50	19/10/07	11.626	11.671					45	1.20	0.108	54.00	5.83	LHS
51	19/10/07	11.628	11.710					82	1.40	0.083	114.80	9.53	LHS
52	19/10/07	11.710	11.800					90	2.00	0.083	180.00	14.94	LHS
53	20/10/07	11.800	11.880					80	1.00	0.083	80.00	6.64	LHS
54	20/10/07	11.911	11.993					82	1.00	0.092	82.00	7.54	LHS
55	20/10/07	12.141	12.176					35	1.20	0.075	42.00	3.15	RHS
56	20/10/07	12.215	12.330					115	1.00	0.083	115.00	9.55	LHS
57	20/10/07	12.338	12.458					120	1.00	0.083	120.00	9.96	LHS
58	20/10/07	12.396	12.440					44	1.40	0.083	61.60	5.11	RHS
59	20/10/07	12.565	12.608					43	1.00	0.083	43.00	3.57	RHS
60	20/10/07	12.983	13.043					60	1.05	0.083	63.00	5.23	LHS
<b>CARRIED FORWARD:</b>							15,175.58				10,981.25	937.27	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 500

**ROAD NAME:** JLN KK-KENINGAU-TENOM

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
<b>BROUGHT FORWARD:</b>							<b>15,175.58</b>				<b>10,981.25</b>	<b>937.27</b>	
61	22/10/07	13.047	13.077					30	1.20	0.075	36.00	2.70	RHS
62	22/10/07	13.292	13.359					67	1.20	0.075	80.40	6.03	RHS
63	22/10/07	13.493	13.588					95	2.00	0.083	190.00	15.77	RHS
64	22/10/07	14.042	14.095					53	1.20	0.083	63.60	5.28	LHS
65	22/10/07	14.345	14.397					52	1.50	0.075	78.00	5.85	LHS
66	22/10/07	14.468	14.776					308	1.40	0.075	431.20	32.34	LHS
67	22/10/07	14.660	14.706					40	1.60	0.083	64.00	5.31	LHS
68	22/10/07	14.796	14.826					30	1.20	0.083	36.00	2.99	LHS
69	22/10/07	15.830	15.943					113	2.80	0.083	316.40	26.26	RHS
70	22/10/07	16.200	16.280					80	2.00	0.075	160.00	12.00	RHS
71	22/10/07	16.300	16.408					108	2.20	0.083	237.60	19.72	RHS
72	22/10/07	18.300	18.350					50	2.00	0.083	100.00	8.30	RHS
73	22/10/07	18.310	18.360					50	2.00	0.083	100.00	8.30	LHS
74	23/10/07	0.178	0.335					157	3.00	0.070	471.00	32.97	LHS
75	23/10/07	0.423	0.847					424	3.00	0.070	1,272.00	89.04	LHS
76	23/10/07	0.863	0.988					125	3.00	0.070	375.00	26.25	LHS
77	23/10/07	1.224	1.355					131	3.00	0.080	393.00	31.44	LHS
78	23/10/07	1.484	1.509					25	3.00	0.060	75.00	4.50	RHS
79	23/10/07	1.500	1.584					84	3.00	0.070	252.00	17.64	LHS
80	23/10/07	1.592	1.702					110	3.00	0.070	330.00	23.10	LHS
81	23/10/07	1.640	1.693					53	3.00	0.080	159.00	12.72	LHS
82	23/10/07	1.931	2.049					118	3.00	0.070	354.00	24.78	LHS
83	23/10/07	1.982	2.044					62	3.00	0.070	186.00	13.02	RHS
84	24/10/07	2.100	2.202					102	3.00	0.060	306.00	18.36	RHS
85	24/10/07	2.046	2.151					105	3.00	0.060	315.00	18.90	LHS
86	24/10/07	2.327	2.431					104	3.00	0.070	312.00	21.84	RHS
87	25/10/07	2.418	2.500					82	3.00	0.050	246.00	12.30	LHS
88	25/10/07	2.581	2.702					121	3.00	0.090	363.00	32.67	RHS
89	25/10/07	2.660	2.730					70	3.00	0.080	210.00	16.80	RHS
90	25/10/07	2.604	2.664					60	3.00	0.080	180.00	14.40	LHS
<b>CARRIED FORWARD:</b>							<b>15,175.58</b>				<b>18,673.45</b>	<b>1,498.85</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 500

**ROAD NAME:** JLN KK-KENINGAU-TENOM

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
<b>BROUGHT FORWARD:</b>							15,175.58				18,673.45	1,498.85	
91	26/10/07	2.753	2.870					117	3.00	0.080	351.00	28.08	RHS
92	26/10/07	2.933	3.003					70	3.00	0.070	210.00	14.70	RHS
93	26/10/07	4.700	4.810					110	3.00	0.090	330.00	29.70	LHS
<b>TOTAL:</b>							15,175.58				19,564.45	1,571.33	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 501

**ROAD NAME:** JALAN KK-PENAMPANG-LOK KAWI

**MONTH:** OCTOBER 2007

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
		BROUGHT FORWARD:					7,372.00				5.76	5.36	
<b>TOTAL:</b>							7,372.00				5.76	5.36	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - LABUAN, FT

**SUMMARY- SHOULDER REPAIR RECORD**

*month : OCTOBER 2007*

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	W.P LABUAN	L 700	JALAN PATAU-PATAU	8,681.10	3,586.00	12,267.10	-	-	-	-	-	-
2	W.P LABUAN	L 700	JALAN POHON BATU	-	-	-	-	-	-	-	-	-
3	W.P LABUAN	L 700	JALAN TUN MUSTAPHA	-	-	-	-	-	-	-	-	-
4	W.P LABUAN	L 704	JALAN MOHD SALLEH	-	-	-	-	-	-	-	-	-
5	W.P LABUAN	L 705	JALAN BEBULOH	7,039.10	-	7,039.10	-	-	-	-	-	-
6	W.P LABUAN	L 706	JALAN RANCHA-RANCHA	-	-	-	-	-	-	-	-	-
7	W.P LABUAN	L 719	JALAN PENGHULU TUAH	-	-	-	-	-	-	-	-	-
8	W.P LABUAN	L 722	JALAN RANCHA-RANCHA LAMA	36.41	-	36.41	-	-	-	-	-	-
9	W.P LABUAN	L 731	JALAN ARSAT	890.42	-	890.42	-	-	-	-	-	-
<b>TOTAL</b>				<b>16,647.03</b>	<b>3,586.00</b>	<b>20,233.03</b>	-	-	-	-	-	-

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - LABUAN, FT  
**R02 SHOULDER REPAIR RECORD**

DISTRICT: W.P LABUAN  
ROUTE NO. L 700  
ROAD NAME: JALAN PATAU-PATAU  
MONTH: OCTOBER 2007

ITEM	DATE	CHAINAGE (KM)		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	<b>8,681.10</b>	-	-	-	-	-	
1	15/10/2007	3600	4270	670.00	4.50	0.15	3,015.00						RHS
2	"	2985	3007	22.00	3.20	0.15	70.40						RHS
3	16/10/2007	1965	2003	38.00	4.00	0.15	152.00						RHS
4	"	1870	1895	25.00	3.10	0.15	77.50						RHS
5	18/10/2007	2000	2038	38.00	2.70	0.15	102.60						LHS
6	"	2122	2140	18.00	3.00	0.15	54.00						LHS
7	"	2790	2792	2.00	4.00	0.15	8.00						LHS
8	"	2851	2856	5.00	2.00	0.15	10.00						LHS
9	22/10/2007	3015	3019	4.00	3.00	0.15	12.00						LHS
10	"	3145	3149	4.00	4.00	0.15	16.00						LHS
11	"	3160	3177	17.00	3.00	0.15	51.00						LHS
12	"	3280	3287	7.00	2.50	0.15	17.50						LHS
<b>TOTAL :</b>							<b>12,267.10</b>						