

RO2

PENYENGGARAAN BAHU
JALAN

(SHOULDER)

LINTASAN RESOURCES SDN. BHD.
SHOULDER REPAIR
GRAND SUMMARY

MONTH: DECEMBER 2007

| DISTRICT | ROUTE NO | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | |
|---------------|----------|---------------------------------------|------------------------|------------------------|------------------------|------------------------|-----------------------|------------------------|-----------------------|------------------------|-----------------------|
| | | | Previous | Current | Cumm. | Previous | | Current | | Cumm. | |
| | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Vol (m ³) | Area (m ²) | Vol (m ³) | Area (m ²) | Vol (m ³) |
| Kota Belud | 01 | Jalan Kota Kinabalu-Kudat | 8,236.05 | 450.00 | 8,686.05 | 360.00 | 36.00 | 0.00 | 0.00 | 360.00 | 36.00 |
| Kota Marudu | 01 | Jalan Kota Kinabalu-Kudat | 1,437.00 | 0.00 | 1,437.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Kudat | 01 | Jalan Kota Kinabalu-Kudat | 7,850.50 | 0.00 | 7,850.50 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Tuaran | 01 | Jalan Kota Kinabalu-Kudat | 13,702.14 | 0.00 | 13,702.14 | 11,133.70 | 1,669.02 | 0.00 | 0.00 | 11,133.70 | 1,669.02 |
| | 22 | Jalan Kota Kinabalu-Sandakan | 23,943.32 | 0.00 | 23,943.32 | 8,661.90 | 1,394.16 | 0.00 | 0.00 | 8,661.90 | 1,394.16 |
| | 503 | Jalan Berungis-Kota Belud | 1,984.53 | 0.00 | 1,984.53 | 26,512.07 | 3,976.81 | 0.00 | 0.00 | 26,512.07 | 3,976.81 |
| Kota Kinabalu | 01 | Jalan Kota Kinabalu-Kudat | 1,679.96 | 0.00 | 1,679.96 | 768.56 | 175.24 | 0.00 | 0.00 | 768.56 | 175.24 |
| | 01 | Jalan Kota Kinabalu-Sindumin | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | 606 | Jalan Susur Sepangar Bay | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | 607 | Jalan Masuk Ke Pelabuhan Baru | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | 608 | Jalan Masuk ke Lapangan Terbang Lama | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Penampang | 01 | Jalan Kota Kinabalu-Sindumin | 0.00 | 0.00 | 0.00 | 277.24 | 41.65 | 0.00 | 0.00 | 277.24 | 41.65 |
| | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 17,840.58 | 380.00 | 18,220.58 | 19,564.45 | 1,571.33 | 0.00 | 0.00 | 19,564.45 | 1,571.33 |
| | 501 | Jalan Kota Kinabalu-Penampang-Lokkawi | 7,372.00 | 280.00 | 7,652.00 | 5.76 | 5.36 | 0.00 | 0.00 | 5.76 | 5.36 |
| Papar | 01 | Jalan Kota Kinabalu-Sindumin | 7,544.21 | 0.00 | 7,544.21 | 8,770.33 | 730.31 | 0.00 | 0.00 | 8,770.33 | 730.31 |
| Ranau | 22 | Jalan Kota Kinabalu-Sandakan | 25,114.45 | 252.50 | 25,366.95 | 3,398.06 | 450.94 | 0.00 | 0.00 | 3,398.06 | 450.94 |
| Tambunan | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 21,742.30 | 0.00 | 21,742.30 | 1,671.26 | 189.29 | 0.00 | 0.00 | 1,671.26 | 189.29 |
| Keningau | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 2,312.40 | 0.00 | 2,312.40 | 374.40 | 36.20 | 0.00 | 0.00 | 374.40 | 36.20 |
| Tenom | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 480.00 | 0.00 | 480.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Beaufort | 01 | Jalan Kota Kinabalu-Sindumin | 7,953.40 | 0.00 | 7,953.40 | 8,271.00 | 857.73 | 0.00 | 0.00 | 8,271.00 | 857.73 |
| | 502 | Jalan Beaufort-Menumbok | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Sipitang | 01 | Jalan Kota Kinabalu-Sindumin | 0.00 | 0.00 | 0.00 | 3,474.50 | 602.48 | 0.00 | 0.00 | 3,474.50 | 602.48 |
| Kuala Penyu | 502 | Jalan Beaufort-Menumbok | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| | | | | | | | | | | | |
| TO TAL | | | 149,192.84 | 1,362.50 | 150,555.34 | 93,243.23 | 11,736.52 | 0.00 | 0.00 | 93,243.23 | 11,736.52 |

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

MONTH : DECEMBER 2007

| ITEM | DISTRICT | ROUTE NO. | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | |
|--------------|-------------|-----------|-----------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
| | | | | PREVIOUS MONTH | CURRENT MONTH | CUM MONTH | PREVIOUS MONTH | | CURRENT MONTH | | CUM MONTH | |
| | | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) |
| 1 | Kota Belud | 01 | Jalan Kota Kinabalu - Kudat | 8,236.05 | 450.00 | 8,686.05 | 360.00 | 36.00 | | | 360.00 | 36.00 |
| 2 | Kota Marudu | 01 | Jalan Kota Kinabalu - Kudat | 1,437.00 | - | 1,437.00 | - | - | - | - | - | - |
| 3 | Kudat | 01 | Jalan Kota Kinabalu - Kudat | 7,850.50 | - | 7,850.50 | - | - | - | - | - | - |
| TOTAL | | | | 17,523.55 | 450.00 | 17,973.55 | 360.00 | 36.00 | - | - | 360.00 | 36.00 |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: KOTA BELUD
ROUTE NO. 01
ROAD NAME: JALAN KOTA KINABALU- KUDAT
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-----------------------------|------------|----------|---------|----------------|-------|-------|-----------------|-----------------|-------|-------|---------------|--------------|---------|
| | | From | To | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | | | (m) | (m) | (m) | (m2) | (m) | (m) | (m) | (m2) | (m3) | |
| BROUGHT FORWARD: | | | | | | | 8,236.05 | | | | 360.00 | 36.00 | |
| 1 | 31/12/2007 | 104.980 | 105.130 | 150.00 | 3.00 | | 450.00 | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| BALANCE END OF DEC : | | | | | | | 8,686.05 | | | | 360.00 | 36.00 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: KOTA MARUDU

ROUTE NO. 01

ROAD NAME: JALAN KOTA KINABALU - KUDAT

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|----------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD: | | | | - | - | - | 1,437.00 | - | - | - | | | |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| BALANCE END OF DEC: | | | | | | | 1,437.00 | | | | 0.00 | 0.00 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: KUDAT
ROUTE NO. 01
ROAD NAME: JALAN KOTA KINABALU - KUDAT
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-----------------------------|------|----------|----|----------------|-------|-------|----------|-----------------|-------|-------|------|--------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m2) | (m) | (m) | (m) | (m2) | (m3) | |
| BROUGHT FORWARD: | | | | - | - | - | 7,850.50 | - | - | - | | | |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| BALANCE END OF NOV : | | | | | | | 7,850.50 | | | | 0.00 | 0.00 | |

LINTASAN RESOURCES SDN. BHD.
PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

Month: December 2007

| ITEM | DISTRICT | ROUTE NO. | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | |
|--------------|---------------|-----------|-----------------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
| | | | | PREVIOUS MONTH | CURRENT MONTH | CUM. MONTH | PREVIOUS MONTH | | CURRENT MONTH | | CUM. MONTH | |
| | | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) |
| 1 | Kota Kinabalu | 01 | Jalan Kota Kinabalu - Kudat | 1,679.96 | - | 1,679.96 | 768.56 | 175.24 | - | - | 768.56 | 175.24 |
| 2 | Tuaran | 01 | Jalan Kota Kinabalu - Kudat | 13,702.14 | - | 13,702.14 | 11,133.70 | 1,669.02 | - | - | 11,133.70 | 1,669.02 |
| 3 | Tuaran | 22 | Jalan Kota Kinabalu - Sandakan | 23,943.32 | - | 23,943.32 | 8,661.90 | 1,394.16 | - | - | 8,661.90 | 1,394.16 |
| 4 | Tuaran | 503 | Jalan Berungis - Kota Belud | 1,984.53 | - | 1,984.53 | 26,512.07 | 3,976.81 | - | - | 26,512.07 | 3,976.81 |
| 5 | Kota Kinabalu | 606 | Jalan Susur Sepangar Bay | - | - | - | - | - | - | - | - | - |
| 6 | Kota Kinabalu | 607 | Jalan Masuk Ke Pelabuhan Baru, KK | - | - | - | - | - | - | - | - | - |
| TOTAL | | | | 41,309.95 | - | 41,309.95 | 47,076.23 | 7,215.23 | - | - | 47,076.23 | 7,215.23 |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: KOTA KINABALU
ROUTE NO. 01
ROAD NAME: JALAN KOTA KINABALU - KUDAT
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|---------------|------|-------------------------|----|----------------|-------|-------|----------|-----------------|-------|-------|--------|--------|---------|
| | | From | To | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | | | (m) | (m) | (m) | (m2) | (m) | (m) | (m) | (m2) | (m3) | |
| | | BROUGHT FORWARD: | | - | - | - | 1,679.96 | - | - | - | 768.56 | 175.24 | |
| TOTAL: | | | | | | | 1,679.96 | | | | 768.56 | 175.24 | |

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: KOTA KINABALU

ROUTE NO. 606

ROAD NAME: JALAN SUSUR SEPANGAR BAY

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|------|-----------------|-------|-------|------|--------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m2) | (m) | (m) | (m) | (m2) | (m3) | |
| BROUGHT FORWARD: | | | | - | - | - | | - | - | - | | | |
| TOTAL : | | | | | | | - | | | | - | - | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: KOTA KINABALU

ROUTE NO. 607

ROAD NAME: JALAN MASUK KE PELABUHAN BARU
KK

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD: | | | | - | - | - | | - | - | - | | | |
| TOTAL : | | | | | | | - | | | | - | - | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: TUARAN

ROUTE NO. 01

ROAD NAME: JALAN KOTA KINABALU - KUDAT

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|----------------|------|-------------------------|----|----------------|--------------|--------------|--------------|-----------------|--------------|--------------|--------------|----------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m2) | Length (m) | Width (m) | Depth (m) | Area (m2) | Volume (m3) | |
| | | BROUGHT FORWARD: | | - | - | - | 13,702.14 | - | - | - | 11,133.70 | 1,669.02 | |
| TOTAL : | | | | | | | 13,702.14 | | | | 11,133.70 | 1,669.02 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: TUARAN
ROUTE NO. 22
ROAD NAME: JALAN KOTA KINABALU - SANDAKAN
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|----------------|------|-------------------------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| | | BROUGHT FORWARD: | | - | - | - | 23,943.32 | - | - | - | 8,661.90 | 1,394.16 | |
| TOTAL : | | | | | | | 23,943.32 | | | | 8,661.90 | 1,394.16 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: TUARAN
ROUTE NO. 503
ROAD NAME: JALAN BERUNGIS - KOTA BELUD
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|----------------|------|-------------------------|----|----------------|--------------|--------------|--------------|-----------------|--------------|--------------|--------------|----------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m2) | Length (m) | Width (m) | Depth (m) | Area (m2) | Volume (m3) | |
| | | BROUGHT FORWARD: | | - | - | - | 1,984.53 | - | - | - | 26,512.07 | 3,976.81 | |
| TOTAL : | | | | | | | 1,984.53 | | | | 26,512.07 | 3,976.81 | |

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

Month : December 2007

| ITEM | DISTRICT | ROUTE NO. | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | |
|--------------|----------|-----------|--------------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
| | | | | PREVIOUS MONTH | CURRENT MONTH | CUM MONTH | PREVIOUS MONTH | | CURRENT MONTH | | CUM MONTH | |
| | | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) |
| 1 | Ranau | 22 | Jalan Kota Kinabalu - Sandakan | 25,114.45 | 252.50 | 25,366.95 | 3,398.06 | 450.94 | - | - | 3,398.06 | 450.94 |
| TOTAL | | | | 25,114.45 | 252.50 | 25,366.95 | 3,398.06 | 450.94 | - | - | 3,398.06 | 450.94 |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: Ranau
ROUTE NO. 22
ROAD NAME: Jalan Kota Kinabalu - Sandakan
MONTH: December 2007

| ITEM | DATE | | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|--|------------|---------|----------|--------|----------------|-------|------------------|-------------------|-----------------|-------|-----------------|-------------------|-------------------|---------|
| | | | From | To | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | | | | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD FROM NOVEMBER 2007: | | | | | | | 25,114.45 | | | | 3,398.06 | 450.94 | | |
| 1 | 18/12/2007 | 136.300 | 99.700 | 99.730 | 30.00 | 1.50 | 0.10 | 45.00 | | | | | LHS | |
| 2 | 19/12/2007 | 136.400 | 99.800 | 99.830 | 30.00 | 1.50 | 0.10 | 45.00 | | | | | LHS | |
| 3 | 22/12/2007 | 136.450 | 99.850 | 99.885 | 35.00 | 1.50 | 0.10 | 52.50 | | | | | LHS | |
| 4 | 26/12/2007 | 120.600 | 84.000 | 84.060 | 60.00 | 1.00 | 0.10 | 60.00 | | | | | RHS | |
| 5 | 27/12/2007 | 133.100 | 96.500 | 96.550 | 50.00 | 1.00 | 0.10 | 50.00 | | | | | RHS | |
| 6 | | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | |
| CARRIED FORWARD: | | | | | | | | 25,366.95 | | | | 3,398.06 | 450.94 | |

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

Month: DECEMBER 2007

| ITEM | DISTRICT | ROUTE NO. | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | | |
|--------------|---------------|-----------|--|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|---|
| | | | | PREVIOUS MONTH | CURRENT MONTH | CUM MONTH | PREVIOUS MONTH | | CURRENT MONTH | | CUM MONTH | | |
| | | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | |
| 1 | Kota Kinabalu | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | - | - | - | - | - | - | - |
| 2 | Penampang | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | 277.24 | 41.65 | - | - | 277.24 | 41.65 | - |
| 3 | Papar | 01 | Jalan Kota Kinabalu - Sindumin | 7,544.71 | - | 7,544.71 | 8,770.33 | 730.31 | - | - | 8,770.33 | 730.31 | - |
| 4 | Penampang | 500 | Jalan Kota Kinabalu - Keningau - Tenom | 17,840.58 | 380.00 | 18,220.58 | 19,564.45 | 1,571.33 | - | - | 19,564.45 | 1,571.33 | - |
| 5 | Penampang | 501 | Jalan Kota Kinabalu - Penampang - Lok Kawi | 7,372.00 | 280.00 | 7,652.00 | 5.76 | 5.36 | - | - | 5.76 | 5.36 | - |
| 6 | Kota Kinabalu | 608 | Jalan Masuk Ke Lapangan Terbang Lama, KK | - | - | - | - | - | - | - | - | - | - |
| TOTAL | | | | 32,757.29 | 660.00 | 33,417.29 | 28,617.78 | 2,348.65 | - | - | 28,617.78 | 2,348.65 | - |

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PENAMPANG

ROUTE NO.: 01

ROAD NAME: JALAN KK-SINDUMIN

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|---------------|------|----------|----|----------------|--------------|--------------|--------------|-----------------|--------------|--------------|--------------|----------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m2) | Length (m) | Width (m) | Depth (m) | Area (m2) | Volume (m3) | |
| | | | | | | | 0.00 | | | | 277.24 | 41.65 | |
| TOTAL: | | | | | | | 0.00 | | | | 277.24 | 41.65 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PAPAR
ROUTE NO.: 01
ROAD NAME: JALAN KK-SINDUMIN
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|------------------|------|----------|----|----------------|--------------|--------------|--------------|-----------------|--------------|--------------|--------------|----------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m2) | Length (m) | Width (m) | Depth (m) | Area (m2) | Volume (m3) | |
| BROUGHT FORWARD: | | | | | | | 7,544.71 | | | | 8,770.33 | 730.31 | |
| TOTAL: | | | | | | | 7,544.71 | | | | 8,770.33 | 730.31 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PENAMPANG
 ROUTE NO.: 500
 ROAD NAME: JLN KK-KENINGAU-TENOM
 MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|----------|----------|--------|----------------|--------------|--------------|------------------|-----------------|--------------|--------------|------------------|-----------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m2) | Length (m) | Width (m) | Depth (m) | Area (m2) | Volume (m3) | |
| BROUGHT FORWARD: | | | | | | | 17,840.58 | | | | 19,564.45 | 1,571.33 | |
| 1 | 12/12/07 | 24.400 | 24.500 | 100 | 2.00 | | 200.00 | | | | 0.00 | 0.00 | RHS |
| 2 | 14/12/07 | 14.950 | 15.010 | 60 | 3.00 | | 180.00 | | | | 0.00 | 0.00 | LHS |
| TOTAL: | | | | | | | 18,220.58 | | | | 19,564.45 | 1,571.33 | |

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PENAMPANG

ROUTE NO.: 501

ROAD NAME: JALAN KK-PENAMPANG-LOK KAWI

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|----------|----------|--------|----------------|--------------|--------------|--------------|-----------------|--------------|--------------|--------------|----------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m2) | Length (m) | Width (m) | Depth (m) | Area (m2) | Volume (m3) | |
| BROUGHT FORWARD: | | | | | | | 7,372.00 | | | | 5.76 | 5.36 | |
| 1 | 04/12/07 | 18.900 | 18.965 | 65 | 2.00 | | 130.00 | | | | 0.00 | 0.00 | RHS |
| 2 | 06/12/07 | 19.500 | 19.550 | 50 | 3.00 | | 150.00 | | | | 0.00 | 0.00 | LHS |
| TOTAL: | | | | | | | 7,652.00 | | | | 5.76 | 5.36 | |

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - SHOULDER REPAIR RECORD

Month : DECEMBER 2007

| ITEM | DISTRICT | ROUTE NO. | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | |
|--------------|----------|-----------|--|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
| | | | | PREVIOUS MONTH | CURRENT MONTH | CUM. MONTH | PREVIOUS MONTH | | CURRENT MONTH | | CUM. MONTH | |
| | | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) |
| 1 | TAMBUNAN | 500 | Jalan Kota Kinabalu - Keningau - Tenom | 21,742.30 | - | 21,742.30 | 1,671.26 | 189.29 | - | - | 1,671.26 | 189.29 |
| 2 | KENINGAU | 500 | Jalan Kota Kinabalu - Keningau - Tenom | 2,312.40 | - | 2,312.40 | 374.40 | 36.20 | - | - | 374.40 | 36.20 |
| 3 | TENOM | 500 | Jalan Kota Kinabalu - Keningau - Tenom | 480.00 | - | 480.00 | - | - | - | - | - | - |
| TOTAL | | | | 24,534.70 | - | 24,534.70 | 2,045.66 | 225.49 | - | - | 2,045.66 | 225.49 |

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: TAMBUNAN

ROUTE NO. 500

ROAD NAME: JLN K. KINABALU - KENINGAU - TENOM

MONTH: December 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|-----------|-----------------|-------|-------|----------|--------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m2) | (m) | (m) | (m) | (m2) | (m3) | |
| BROUGHT FORWARD: | | | | | | | 21,742.30 | | | | 1,671.26 | 189.29 | |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| TOTAL | | | | | | | 21,742.30 | | | | 1,671.26 | 189.29 | |

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: KENINGAU

ROUTE NO. 500

ROAD NAME: JLN K. KINABALU - KENINGAU - TENOM

MONTH: December 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | From | To | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | | | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD: | | | | | | | 2,312.40 | | | | 374.40 | 36.20 | |
| 1 | | | | | | | 0.00 | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| TOTAL | | | | | | | 2,312.40 | | | | 374.40 | 36.20 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: TENOM

ROUTE NO. 500

ROAD NAME: JLN K. KINABALU - KENINGAU - TENOM

MONTH: December 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD: | | | | | | | 480.00 | | | | 0.00 | 0.00 | |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| TOTAL | | | | | | | 480.00 | | | | 0.00 | 0.00 | |

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

Month : DECEMBER 2007

| ITEM | DISTRICT | ROUTE NO. | ROAD NAME | EARTH SHOULDER | | | GRAVEL SHOULDER | | | | | |
|--------------|-------------|-----------|--------------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
| | | | | PREVIOUS MONTH | CURRENT MONTH | CUM. MONTH | PREVIOUS MONTH | | CURRENT MONTH | | CUM. MONTH | |
| | | | | Area (m ²) | Area (m ²) | Area (m ²) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) | Area (m ²) | Volume (m ³) |
| 1 | Beaufort | 01 | Jalan Kota Kinabalu - Sindumin | 7,953.40 | - | 7,953.40 | 8,271.00 | 857.73 | - | - | 8,271.00 | 857.73 |
| 2 | Beaufort | 502 | Jalan Beaufort - Menumbok | - | - | - | - | - | - | - | - | - |
| 3 | Sipitang | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | 3,474.50 | 602.48 | - | - | 3,474.50 | 602.48 |
| 4 | Kuala Penyu | 502 | Jalan Beaufort - Menumbok | - | - | - | - | - | - | - | - | - |
| TOTAL | | | | 7,953.40 | - | 7,953.40 | 11,745.50 | 1,460.21 | - | - | 11,745.50 | 1,460.21 |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: BEAUFORT

ROUTE NO. 01

ROAD NAME: JALAN KOTA KINABALU - SINDUMIN

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | From | To | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | | | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD: | | | | - | - | - | 7,953.40 | - | - | - | 8271.00 | 857.73 | - |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| CARRIED FORWARD: | | | | | | | 7,953.40 | | | | 8,271.00 | 857.73 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: SIPITANG
 ROUTE NO. 01
 ROAD NAME: JALAN KOTA KINABALU - SINDUMIN
 MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS | |
|-------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|--|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | | |
| | | From | To | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | | |
| BROUGHT FORWARD: | | | | - | - | - | 0.00 | - | - | - | 3,474.50 | 602.48 | - | |
| 1 | | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | | |
| CARRIED FORWARD: | | | | | | | 0.00 | | | | 3,474.50 | 602.48 | | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: BEAUFORT

ROUTE NO. 502

ROAD NAME: JALAN BEAUFORT - MENUMBOK

MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|-------|-------|-------------------|-----------------|-------|-------|-------------------|-------------------|---------|
| | | | | Length | Width | Depth | Area | Length | Width | Depth | Area | Volume | |
| | | From | To | (m) | (m) | (m) | (m ²) | (m) | (m) | (m) | (m ²) | (m ³) | |
| BROUGHT FORWARD: | | | | - | - | - | 0.00 | - | - | - | 0.00 | 0.00 | - |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| CARRIED FORWARD: | | | | | | | 0.00 | | | | 0.00 | 0.00 | |

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: KUALA PENYU
ROUTE NO. 502
ROAD NAME: JALAN BEAUFORT - MENUMBOK
MONTH: DECEMBER 2007

| ITEM | DATE | CHAINAGE | | EARTH SHOULDER | | | | GRAVEL SHOULDER | | | | | REMARKS |
|-------------------------|------|----------|----|----------------|--------------|--------------|---------------------------|-----------------|--------------|--------------|---------------------------|-----------------------------|---------|
| | | From | To | Length (m) | Width (m) | Depth (m) | Area (m ²) | Length (m) | Width (m) | Depth (m) | Area (m ²) | Volume (m ³) | |
| BROUGHT FORWARD: | | | | - | - | - | 0.00 | - | - | - | 0.00 | 0.00 | - |
| 1 | | | | | | | | | | | | | |
| 2 | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | |
| 21 | | | | | | | | | | | | | |
| 22 | | | | | | | | | | | | | |
| 23 | | | | | | | | | | | | | |
| 24 | | | | | | | | | | | | | |
| 25 | | | | | | | | | | | | | |
| 26 | | | | | | | | | | | | | |
| 27 | | | | | | | | | | | | | |
| 28 | | | | | | | | | | | | | |
| 29 | | | | | | | | | | | | | |
| 30 | | | | | | | | | | | | | |
| CARRIED FORWARD: | | | | | | | 0.00 | | | | 0.00 | 0.00 | |