

# RO2

(SHOULDER)

**LINTASAN RESOURCES SDN. BHD.**  
**SHOULDER REPAIR**  
**GRAND SUMMARY**

MONTH: FEBRUARY 2006

| DISTRICT      | ROUTE NO | ROAD NAME                             | EARTH SHOULDER         |                        |                        | GRAVEL SHOULDER        |                       |                        |                       |                        |                       |
|---------------|----------|---------------------------------------|------------------------|------------------------|------------------------|------------------------|-----------------------|------------------------|-----------------------|------------------------|-----------------------|
|               |          |                                       | Previous               | Current                | Cumm.                  | Previous               |                       | Current                |                       | Cumm.                  |                       |
|               |          |                                       | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Vol (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Vol (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Vol (m <sup>3</sup> ) |
| Kota Belud    | 01       | Jalan Kota Kinabalu-Kudat             | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Kota Marudu   | 01       | Jalan Kota Kinabalu-Kudat             | 0.00                   | 425.00                 | 425.00                 | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Kudat         | 01       | Jalan Kota Kinabalu-Kudat             | 1,401.00               | 400.00                 | 1,801.00               | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Tuaran        | 01       | Jalan Kota Kinabalu-Kudat             | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 22       | Jalan Kota Kinabalu-Sandakan          | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 503      | Jalan Berungis-Kota Belud             | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Kota Kinabalu | 01       | Jalan Kota Kinabalu-Kudat             | 25,137.80              | 1,662.20               | 26,800.00              | 0.00                   | 0.00                  | 1,263.20               | 343.64                | 1,263.20               | 343.64                |
|               | 01       | Jalan Kota Kinabalu-Sindumin          | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 606      | Jalan Susur Sepangar Bay              | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 607      | Jalan Masuk Ke Pelabuhan Baru         | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 608      | Jalan Masuk ke Lapangan Terbang Lama  | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Penampang     | 01       | Jalan Kota Kinabalu-Sindumin          | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 500      | Jalan Kota Kinabalu-Keningau-Tenom    | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 501      | Jalan Kota Kinabalu-Penampang-Lokkawi | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Papar         | 01       | Jalan Kota Kinabalu-Sindumin          | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Ranau         | 22       | Jalan Kota Kinabalu-Sandakan          | 346.00                 | 106.50                 | 452.50                 | 0.00                   | 0.00                  | 400.00                 | 48.00                 | 400.00                 | 48.00                 |
| Tambunan      | 500      | Jalan Kota Kinabalu-Keningau-Tenom    | 0.00                   | 2,080.40               | 2,080.40               | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Keningau      | 500      | Jalan Kota Kinabalu-Keningau-Tenom    | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Tenom         | 500      | Jalan Kota Kinabalu-Keningau-Tenom    | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Beaufort      | 01       | Jalan Kota Kinabalu-Sindumin          | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               | 502      | Jalan Beaufort-Menumbok               | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Sipitang      | 01       | Jalan Kota Kinabalu-Sindumin          | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
| Kuala Penyu   | 502      | Jalan Beaufort-Menumbok               | 0.00                   | 0.00                   | 0.00                   | 0.00                   | 0.00                  | 0.00                   | 0.00                  | 0.00                   | 0.00                  |
|               |          |                                       |                        |                        |                        |                        |                       |                        |                       |                        |                       |
|               |          |                                       |                        |                        |                        |                        |                       |                        |                       |                        |                       |
| <b>TOTAL</b>  |          |                                       | 26,884.80              | 4,674.10               | 31,558.90              | 0.00                   | 0.00                  | 1,663.20               | 391.64                | 1,663.20               | 391.64                |

**LINTASAN RESOURCES SDN. BHD.**

*PROJECT DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY- SHOULDER REPAIR RECORD**

Month : February 2006

| ITEM         | DISTRICT    | ROUTE NO. | ROAD NAME                   | EARTH SHOULDER         |                        |                        | GRAVEL SHOULDER        |                          |                        |                          |                        |                          |   |
|--------------|-------------|-----------|-----------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|---|
|              |             |           |                             | PREVIOUS MONTH         | CURRENT MONTH          | CUM MONTH              | PREVIOUS MONTH         |                          | CURRENT MONTH          |                          | CUM MONTH              |                          |   |
|              |             |           |                             | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) |   |
| 1            | Kota Belud  | 01        | Jalan Kota Kinabalu - Kudat | -                      | -                      | -                      | -                      | -                        | -                      | -                        | -                      | -                        | - |
| 2            | Kota Marudu | 01        | Jalan Kota Kinabalu - Kudat | -                      | 425.00                 | 425.00                 | -                      | -                        | -                      | -                        | -                      | -                        | - |
| 3            | Kudat       | 01        | Jalan Kota Kinabalu - Kudat | 1,401.00               | 400.00                 | 1,801.00               | -                      | -                        | -                      | -                        | -                      | -                        | - |
| <b>TOTAL</b> |             |           |                             | <b>1,401.00</b>        | <b>825.00</b>          | <b>2,226.00</b>        | -                      | -                        | -                      | -                        | -                      | -                        | - |

**LINTASAN RESOURCES SDN. BHD.**

*PROJECT DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY- SHOULDER REPAIR RECORD**

Month: FEBRUARY 2006

| ITEM         | DISTRICT      | ROUTE NO. | ROAD NAME                         | EARTH SHOULDER         |                        |                        | GRAVEL SHOULDER        |                          |                        |                          |                        |                          |
|--------------|---------------|-----------|-----------------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
|              |               |           |                                   | PREVIOUS MONTH         | CURRENT MONTH          | CUM MONTH              | PREVIOUS MONTH         |                          | CURRENT MONTH          |                          | CUM MONTH              |                          |
|              |               |           |                                   | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) |
| 1            | Kota Kinabalu | 01        | Jalan Kota Kinabalu - Kudat       | 25,137.80              | 1,662.20               | 26,800.00              | -                      | -                        | 1,263.20               | 343.64                   | 1,263.20               | 343.64                   |
| 2            | Tuaran        | 01        | Jalan Kota Kinabalu - Kudat       | -                      | -                      | -                      | -                      | -                        | -                      | -                        | -                      | -                        |
| 3            | Tuaran        | 22        | Jalan Kota Kinabalu - Sandakan    | -                      | -                      | -                      | -                      | -                        | -                      | -                        | -                      | -                        |
| 4            | Tuaran        | 503       | Jalan Berungis - Kota Belud       | -                      | -                      | -                      | -                      | -                        | -                      | -                        | -                      | -                        |
| 5            | Kota Kinabalu | 606       | Jalan Susur Sepangar Bay          | -                      | -                      | -                      | -                      | -                        | -                      | -                        | -                      | -                        |
| 6            | Kota Kinabalu | 607       | Jalan Masuk Ke Pelabuhan Baru, KK | -                      | -                      | -                      | -                      | -                        | -                      | -                        | -                      | -                        |
| <b>TOTAL</b> |               |           |                                   | <b>25,137.80</b>       | <b>1,662.20</b>        | <b>26,800.00</b>       | <b>-</b>               | <b>-</b>                 | <b>1,263.20</b>        | <b>343.64</b>            | <b>1,263.20</b>        | <b>343.64</b>            |

**LINTASAN RESOURCES SDN. BHD.**

*PROVIDER OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY- SHOULDER REPAIR RECORD**

Month : February 2006

| ITEM         | DISTRICT | ROUTE NO. | ROAD NAME                      | EARTH SHOULDER         |                        |                        | GRAVEL SHOULDER        |                          |                        |                          |                        |                          |
|--------------|----------|-----------|--------------------------------|------------------------|------------------------|------------------------|------------------------|--------------------------|------------------------|--------------------------|------------------------|--------------------------|
|              |          |           |                                | PREVIOUS MONTH         | CURRENT MONTH          | CUM. MONTH             | PREVIOUS MONTH         |                          | CURRENT MONTH          |                          | CUM. MONTH             |                          |
|              |          |           |                                | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) | Area (m <sup>2</sup> ) | Volume (m <sup>3</sup> ) |
| 1            | Ranau    | 22        | Jalan Kota Kinabalu - Sandakan | 346.00                 | 106.50                 | 452.50                 | -                      | -                        | 400.00                 | 48.00                    | 400.00                 | 48.00                    |
| <b>TOTAL</b> |          |           |                                | <b>346.00</b>          | <b>106.50</b>          | <b>452.50</b>          | <b>-</b>               | <b>-</b>                 | <b>400.00</b>          | <b>48.00</b>             | <b>400.00</b>          | <b>48.00</b>             |