

R05

(BRIDGE AND CULVERT)

LINTASAN RESOURCES SDN. BHD.
CULVERT CLEARING
GRAND SUMMARY

MONTH: FEBRUARY 2006

| DISTRICT | ROUTE NO. | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|---------------|-----------|--|-------------|------------|------------|-----------|-----------|------------|--------------------|-----------|-----------|
| | | | Previous | Current | Cumm. | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| Kota Belud | 01 | Jalan Kota Kinabalu-Kudat | 12 | 5 | 17 | 2 | 0 | 2 | 1 | 0 | 1 |
| Kota Marudu | 01 | Jalan Kota Kinabalu-Kudat | 0 | 25 | 25 | 0 | 18 | 18 | 0 | 4 | 4 |
| Kudat | 01 | Jalan Kota Kinabalu-Kudat | 14 | 0 | 14 | 1 | 0 | 1 | 0 | 0 | 0 |
| Tuaran | 01 | Jalan Kota Kinabalu-Kudat | 22 | 23 | 45 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 22 | Jalan Kota Kinabalu-Sandakan | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 503 | Jalan Berungis-Kota Belud | 7 | 61 | 68 | 1 | 2 | 3 | 0 | 2 | 2 |
| Kota Kinabalu | 01 | Jalan Kota Kinabalu-Kudat | 59 | 0 | 59 | 12 | 0 | 12 | 4 | 0 | 4 |
| | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 606 | Jalan Susur Sepangar Bay | 0 | 43 | 43 | 0 | 5 | 5 | 0 | 1 | 1 |
| | 607 | Jalan Masuk Ke Pelabuhan Baru | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 608 | Jalan Masuk Ke Lapangan Terbang Lama | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Penampang | 01 | Jalan Kota Kinabalu-Sindumin | 20 | 0 | 20 | 0 | 0 | 0 | 4 | 0 | 4 |
| | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 0 | 6 | 6 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 501 | Jalan Kota Kinabalu-Penampang-Lok Kawi | 7 | 0 | 7 | 0 | 0 | 0 | 0 | 0 | 0 |
| Papar | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 20 | 20 | 0 | 39 | 39 | 0 | 13 | 13 |
| Ranau | 22 | Jalan Kota Kinabalu-Sandakan | 62 | 35 | 97 | 2 | 2 | 4 | 3 | 0 | 3 |
| Tambunam | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 39 | 90 | 129 | 15 | 1 | 16 | 0 | 5 | 5 |
| Keningau | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tenom | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Beaufort | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 502 | Jalan Beaufort-Menumbok | 20 | 0 | 20 | 2 | 0 | 2 | 0 | 0 | 0 |
| Sipitang | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Kuala Penyu | 502 | Jalan Beaufort-Menumbok | 3 | 66 | 69 | 0 | 30 | 30 | 0 | 1 | 1 |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| TOTAL | | | 265 | 374 | 639 | 35 | 97 | 132 | 12 | 26 | 38 |

LINTASAN RESOURCES SDN. BHD.
 PROJECTS DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|----------------|-------------|----------|-----------------------------|-------------------|------------------|----------------|-------------------|------------------|----------------|--------------------|------------------|----------------|
| | | | | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) |
| 1 | Kota Belud | 01 | Jalan Kota Kinabalu - Kudat | 12 | 5 | 17 | 2 | - | 2 | 1 | - | 1 |
| 2 | Kota Marudu | 01 | Jalan Kota Kinabalu - Kudat | - | 25 | 25 | - | 18 | 18 | - | 4 | 4 |
| 3 | Kudat | 01 | Jalan Kota Kinabalu - Kudat | 14 | - | 14 | 1 | - | 1 | - | - | - |
| TOTAL : | | | | 26 | 30 | 56 | 3 | 18 | 21 | 1 | 4 | 5 |

LINTASAN RESOURCES SDN. BHD.
PROPRIETARY OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|----------------|---------------|----------|-----------------------------------|-------------------|------------------|----------------|-------------------|------------------|----------------|--------------------|------------------|----------------|
| | | | | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) |
| 1 | Kota Kinabalu | 01 | Jalan Kota Kinabalu - Kudat | 59 | - | 59 | 12 | - | 12 | 4 | - | 4 |
| 2 | Tuaran | 01 | Jalan Kota Kinabalu - Kudat | 22 | 23 | 45 | - | - | - | - | - | - |
| 3 | Tuaran | 22 | Jalan Kota Kinabalu - Sandakan | - | - | - | - | - | - | - | - | - |
| 4 | Tuaran | 503 | Jalan Berungis - Kota Belud | 7 | 61 | 68 | 1 | 2 | 3 | - | 2 | 2 |
| 5 | Kota Kinabalu | 606 | Jalan Susur Sepangar Bay | - | 43 | 43 | - | 5 | 5 | - | 1 | 1 |
| 6 | Kota Kinabalu | 607 | Jalan Masuk Ke Pelabuhan Baru, KK | - | - | - | - | - | - | - | - | - |
| TOTAL : | | | | 88 | 127 | 215 | 13 | 7 | 20 | 4 | 3 | 7 |

LINTASAN RESOURCES SDN. BHD.
PROJEK/PROJECT OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|----------------|----------|----------|--------------------------------|-------------|-----------|-----------|-----------|----------|----------|--------------------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Ranau | 22 | Jalan Kota Kinabalu - Sandakan | 62 | 35 | 97 | 2 | 2 | 4 | 3 | - | 3 |
| TOTAL : | | | | 62 | 35 | 97 | 2 | 2 | 4 | 3 | - | 3 |

LINTASAN RESOURCES SDN. BHD.
PROJECTS DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|----------------|---------------|----------|--|-------------------|------------------|----------------|-------------------|------------------|----------------|--------------------|------------------|----------------|
| | | | | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) |
| 1 | Kota Kinabalu | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | - | - | - | - | - | - |
| 2 | Penampang | 01 | Jalan Kota Kinabalu - Sindumin | 20 | - | 20 | - | - | - | 4 | - | 4 |
| 3 | Papar | 01 | Jalan Kota Kinabalu - Sindumin | - | 20 | 20 | - | 39 | 39 | - | 13 | 13 |
| 4 | Penampang | 500 | Jalan Kota Kinabalu - Keningau - Tenom | - | 6 | 6 | - | - | - | - | - | - |
| 5 | Penampang | 501 | Jalan Kota Kinabalu - Penampang - Lok Kawi | 7 | - | 7 | - | - | - | - | - | - |
| 6 | Kota Kinabalu | 608 | Jalan Masuk Ke Lapangan Terbang Lama, KK | - | - | - | - | - | - | - | - | - |
| TOTAL : | | | | 27 | 26 | 53 | - | 39 | 39 | 4 | 13 | 17 |

LINTASAN RESOURCES SDN. BHD.
 PROJECTS DIVISION OF WEST COAST STATE FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|----------------|----------|----------|--|-------------------|------------------|----------------|-------------------|------------------|----------------|--------------------|------------------|----------------|
| | | | | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) |
| 1 | Tambunan | 500 | Jalan Kota Kinabalu - Keningau - Tenom | 39 | 90 | 129 | 15 | 1 | 16 | - | 5 | 5 |
| 2 | Keningau | 500 | Jalan Kota Kinabalu - Keningau - Tenom | - | - | - | - | - | - | - | - | - |
| 3 | Tenom | 500 | Jalan Kota Kinabalu - Keningau - Tenom | - | - | - | - | - | - | - | - | - |
| TOTAL : | | | | 39 | 90 | 129 | 15 | 1 | 16 | - | 5 | 5 |

LINTASAN RESOURCES SDN. BHD.
PROJEK/PROJECT OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | Single Cell | | | Twin Cell | | | 3 / 4 / 5 / 6-Cell | | |
|----------------|-------------|----------|--------------------------------|-------------------|------------------|----------------|-------------------|------------------|----------------|--------------------|------------------|----------------|
| | | | | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) | Previous (No.) | Current (No.) | Cumm. (No.) |
| 1 | Beaufort | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | - | - | - | - | - | - |
| 2 | Sipitang | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | - | - | - | - | - | - |
| 3 | Beaufort | 502 | Jalan Beaufort - Menumbok | 20 | - | 20 | 2 | - | 2 | - | - | - |
| 4 | Kuala Penyu | 502 | Jalan Beaufort - Menumbok | 3 | 66 | 69 | - | 30 | 30 | - | 1 | 1 |
| TOTAL : | | | | 23 | 66 | 89 | 2 | 30 | 32 | - | 1 | 1 |

LINTASAN RESOURCES SDN. BHD.
BRIDGES
GRAND SUMMARY

MONTH: FEBRUARY 2006

| DISTRICT | ROUTE NO. | ROAD NAME | General Cleaning | | | Painting | | |
|---------------|-----------|--|------------------|-----------|-----------|----------|----------|----------|
| | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| Kota Belud | 01 | Jalan Kota Kinabalu-Kudat | 0 | 0 | 0 | 0 | 0 | 0 |
| Kota Marudu | 01 | Jalan Kota Kinabalu-Kudat | 4 | 5 | 9 | 0 | 0 | 0 |
| Kudat | 01 | Jalan Kota Kinabalu-Kudat | 2 | 0 | 2 | 0 | 0 | 0 |
| Tuaran | 01 | Jalan Kota Kinabalu-Kudat | 1 | 0 | 1 | 0 | 0 | 0 |
| | 22 | Jalan Kota Kinabalu-Sandakan | 0 | 0 | 0 | 0 | 0 | 0 |
| | 503 | Jalan Berungis-Kota Belud | 0 | 2 | 2 | 0 | 0 | 0 |
| Kota Kinabalu | 01 | Jalan Kota Kinabalu-Kudat | 4 | 0 | 4 | 0 | 0 | 0 |
| | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 0 | 0 | 0 | 0 | 0 |
| | 606 | Jalan Susur Sepangar Bay | 0 | 1 | 1 | 0 | 0 | 0 |
| | 607 | Jalan Masuk Ke Pelabuhan Baru | 0 | 0 | 0 | 0 | 0 | 0 |
| | 608 | Jalan Masuk Ke Lapangan Terbang Lama | 0 | 0 | 0 | 0 | 0 | 0 |
| Penampang | 01 | Jalan Kota Kinabalu-Sindumin | 4 | 0 | 4 | 0 | 0 | 0 |
| | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 0 | 2 | 2 | 0 | 0 | 0 |
| | 501 | Jalan Kota Kinabalu-Penampong-Lok Kawi | 0 | 0 | 0 | 0 | 0 | 0 |
| Papar | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 7 | 7 | 0 | 0 | 0 |
| Ranau | 22 | Jalan Kota Kinabalu-Sandakan | 3 | 1 | 4 | 3 | 1 | 4 |
| Tambunam | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 2 | 2 | 4 | 0 | 0 | 0 |
| Keningau | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 0 | 0 | 0 | 0 | 0 | 0 |
| Tenom | 500 | Jalan Kota Kinabalu-Keningau-Tenom | 0 | 0 | 0 | 0 | 0 | 0 |
| Beaufort | 01 | Jalan Kota Kinabalu-Sindumin | 4 | 0 | 4 | 4 | 0 | 4 |
| | 502 | Jalan Beaufort-Menumbok | 0 | 0 | 0 | 0 | 0 | 0 |
| Sipitang | 01 | Jalan Kota Kinabalu-Sindumin | 0 | 0 | 0 | 0 | 0 | 0 |
| Kuala Penyu | 502 | Jalan Beaufort-Menumbok | 0 | 0 | 0 | 0 | 0 | 0 |
| | | | | | | | | |
| | | | | | | | | |
| TOTAL | | | 24 | 20 | 44 | 7 | 1 | 8 |

LINTASAN RESOURCES SDN. BHD.

PROVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | General Maintenance | | | Painting | | |
|----------------|-------------|----------|-----------------------------|---------------------|----------|-----------|----------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Kota Belud | 01 | Jalan Kota Kinabalu - Kudat | - | - | - | - | - | - |
| 2 | Kota Marudu | 01 | Jalan Kota Kinabalu - Kudat | 4 | 5 | 9 | - | - | - |
| 3 | Kudat | 01 | Jalan Kota Kinabalu - Kudat | 2 | - | 2 | - | - | - |
| TOTAL : | | | | 6 | 5 | 11 | - | - | - |

LINTASAN RESOURCES SDN. BHD.

PROVIDER OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | General Maintenance | | | Painting | | |
|----------------|---------------|----------|-----------------------------------|---------------------|----------|----------|----------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Kota Kinabalu | 01 | Jalan Kota Kinabalu - Kudat | 4 | - | 4 | - | - | - |
| 2 | Tuaran | 01 | Jalan Kota Kinabalu - Kudat | 1 | - | 1 | - | - | - |
| 3 | Tuaran | 22 | Jalan Kota Kinabalu - Sandakan | - | - | - | - | - | - |
| 4 | Tuaran | 503 | Jalan Berungis - Kota Belud | - | 2 | 2 | - | - | - |
| 5 | Kota Kinabalu | 606 | Jalan Susur Sepangar Bay | - | 1 | 1 | - | - | - |
| 6 | Kota Kinabalu | 607 | Jalan Masuk Ke Pelabuhan Baru, KK | - | - | - | - | - | - |
| TOTAL : | | | | 5 | 3 | 8 | - | - | - |

LINTASAN RESOURCES SDN. BHD.

PROVIDER OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | General Maintenance | | | Painting | | |
|----------------|----------|----------|--------------------------------|---------------------|----------|----------|----------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Ranau | 22 | Jalan Kota Kinabalu - Sandakan | 3 | 1 | 4 | 3 | 1 | 4 |
| TOTAL : | | | | 3 | 1 | 4 | 3 | 1 | 4 |

LINTASAN RESOURCES SDN. BHD.

PROVIDER OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | General Maintenance | | | Painting | | |
|----------------|---------------|----------|--|---------------------|----------|-----------|----------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Kota Kinabalu | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | - | - | - |
| 2 | Penampang | 01 | Jalan Kota Kinabalu - Sindumin | 4 | - | 4 | - | - | - |
| 3 | Papar | 01 | Jalan Kota Kinabalu - Sindumin | - | 7 | 7 | - | - | - |
| 4 | Penampang | 500 | Jalan Kota Kinabalu - Keningau - Tenom | - | 2 | 2 | - | - | - |
| 5 | Penampang | 501 | Jalan Kota Kinabalu - Penampang - Lok Kawi | - | - | - | - | - | - |
| 6 | Kota Kinabalu | 608 | Jalan Masuk Ke Lapangan Terbang Lama, KK | - | - | - | - | - | - |
| TOTAL : | | | | 4 | 9 | 13 | - | - | - |

LINTASAN RESOURCES SDN. BHD.

PROVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | General Maintenance | | | Painting | | |
|----------------|----------|----------|--|---------------------|----------|----------|----------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Tambunan | 500 | Jalan Kota Kinabalu - Keningau - Tenom | 2 | 2 | 4 | - | - | - |
| 2 | Keningau | 500 | Jalan Kota Kinabalu - Keningau - Tenom | - | - | - | - | - | - |
| 3 | Tenom | 500 | Jalan Kota Kinabalu - Keningau - Tenom | - | - | - | - | - | - |
| TOTAL : | | | | 2 | 2 | 4 | - | - | - |

LINTASAN RESOURCES SDN. BHD.

PROVISION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : February 2006

| ITEM | DISTRICT | ROUTE NO | ROAD NAME | General Maintenance | | | Painting | | |
|----------------|-------------|----------|--------------------------------|---------------------|----------|----------|----------|----------|----------|
| | | | | Previous | Current | Cumm. | Previous | Current | Cumm. |
| | | | | (No.) | (No.) | (No.) | (No.) | (No.) | (No.) |
| 1 | Beaufort | 01 | Jalan Kota Kinabalu - Sindumin | 4 | - | 4 | 4 | - | 4 |
| 2 | Sipitang | 01 | Jalan Kota Kinabalu - Sindumin | - | - | - | - | - | - |
| 3 | Beaufort | 502 | Jalan Beaufort - Menumbok | - | - | - | - | - | - |
| 4 | Kuala Penyu | 502 | Jalan Beaufort - Menumbok | - | - | - | - | - | - |
| TOTAL : | | | | 4 | - | 4 | 4 | - | 4 |