

R05

(BRIDGE AND CULVERT)

LINTASAN RESOURCES SDN. BHD.
CULVERT CLEARING
GRAND SUMMARY

MONTH: JULY 2006

DISTRICT	ROUTE NO.	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
			Previous	Current	Cumm.	Previous	Current	Cumm.	Previous	Current	Cumm.
			(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
Kota Belud	01	Jalan Kota Kinabalu-Kudat	84	19	103	6	3	9	2	0	2
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	25	7	32	18	7	25	4	1	5
Kudat	01	Jalan Kota Kinabalu-Kudat	87	63	150	38	9	47	1	1	2
Tuaran	01	Jalan Kota Kinabalu-Kudat	136	19	155	4	0	4	0	0	0
	22	Jalan Kota Kinabalu-Sandakan	76	0	76	3	0	3	0	0	0
	503	Jalan Berungis-Kota Belud	68	31	99	3	2	5	2	0	2
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	116	38	154	20	6	26	8	3	11
	01	Jalan Kota Kinabalu-Sindumin	26	0	26	10	0	10	0	0	0
	501	Jalan Kota Kinabalu-Penampang-Lok Kawi	2	0	2	2	0	2	0	0	0
	606	Jalan Susur Sepangar Bay	43	0	43	5	0	5	1	0	1
	607	Jalan Masuk Ke Pelabuhan Baru	3	0	3	0	0	0	0	0	0
	608	Jalan Masuk Ke Lapangan Terbang Lama	9	0	9	2	0	2	0	0	0
Penampang	01	Jalan Kota Kinabalu-Sindumin	20	29	49	0	0	0	4	4	8
	500	Jalan Kota Kinabalu-Keningau-Tenom	118	0	118	5	0	5	0	0	0
	501	Jalan Kota Kinabalu-Penampang-Lok Kawi	47	4	51	3	0	3	0	0	0
Papar	01	Jalan Kota Kinabalu-Sindumin	106	0	106	51	0	51	14	0	14
Ranau	22	Jalan Kota Kinabalu-Sandakan	300	62	362	17	2	19	4	3	7
Tambunam	500	Jalan Kota Kinabalu-Keningau-Tenom	165	48	213	18	8	26	5	0	5
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	123	0	123	15	0	15	3	0	3
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	46	0	46	9	0	9	5	0	5
Beaufort	01	Jalan Kota Kinabalu-Sindumin	100	0	100	55	0	55	30	0	30
	502	Jalan Beaufort-Menumbok	40	12	52	4	2	6	0	0	0
Sipitang	01	Jalan Kota Kinabalu-Sindumin	62	0	62	18	0	18	3	0	3
Kuala Penyu	502	Jalan Beaufort-Menumbok	69	14	83	30	10	40	1	0	1
TOTAL			1871	346	2217	336	49	385	87	12	99

LINTASAN RESOURCES SDN. BHD.
 PROJECTS DIVISION OF WEST COAST STATE FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : July 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			3 / 4 / 5 / 6-Cell		
				Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	84	19	103	6	3	9	2	-	2
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	25	7	32	18	7	25	4	1	5
3	Kudat	01	Jalan Kota Kinabalu - Kudat	87	63	150	38	9	47	1	1	2
TOTAL :				196	89	285	62	19	81	7	2	9

LINTASAN RESOURCES SDN. BHD.

PAJAJARAN OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month: July 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous	Current	Cumm.	Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	116	38	154	20	6	26	8	3	11
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	136	19	155	4	-	4	-	-	-
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	76	-	76	3	-	3	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	68	31	99	3	2	5	2	-	2
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	43	-	43	5	-	5	1	-	1
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	3	-	3	-	-	-	-	-	-
TOTAL :				442	88	530	35	8	43	11	3	14

LINTASAN RESOURCES SDN. BHD.
PROGRESS REPORT OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : July 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	26	-	26	10	-	10	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	20	29	49	-	-	-	4	4	8
3	Papar	01	Jalan Kota Kinabalu - Sindumin	106	-	106	51	-	51	14	-	14
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	118	-	118	5	-	5	-	-	-
5	Kota Kinabalu	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	2	-	2	2	-	2	-	-	-
6	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	47	4	51	3	-	3	-	-	-
7	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	9	-	9	2	-	2	-	-	-
TOTAL :				328	33	361	73	-	73	18	4	22

LINTASAN RESOURCES SDN. BHD.
 PROJECTS DIVISION OF WEST COAST STATE FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : JULY 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)
1	Tambunan	500	Jalan Kota Kinabalu - Keningau - Tenom	165	48	213	18	8	26	5	-	5
2	Keningau	500	Jalan Kota Kinabalu - Keningau - Tenom	123	-	123	15	-	15	3	-	3
3	Tenom	500	Jalan Kota Kinabalu - Keningau - Tenom	46	-	46	9	-	9	5	-	5
TOTAL :				334	48	382	42	8	50	13	-	13

LINTASAN RESOURCES SDN. BHD.
BRIDGES
GRAND SUMMARY

MONTH: JULY 2006

DISTRICT	ROUTE NO.	ROAD NAME	General Cleaning			Painting		
			Previous	Current	Cumm.	Previous	Current	Cumm.
			(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
Kota Belud	01	Jalan Kota Kinabalu-Kudat	9	4	13	0	0	0
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	9	4	13	0	0	0
Kudat	01	Jalan Kota Kinabalu-Kudat	2	2	4	0	0	0
Tuaran	01	Jalan Kota Kinabalu-Kudat	6	1	7	0	0	0
	22	Jalan Kota Kinabalu-Sandakan	0	0	0	0	0	0
	503	Jalan Berungis-Kota Belud	2	1	3	0	0	0
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	9	4	13	5	0	5
	01	Jalan Kota Kinabalu-Sindumin	0	0	0	0	0	0
	501	Jalan Kota Kinabalu-Penampong-Lok Kawi	3	0	3	0	0	0
	606	Jalan Susur Sepangar Bay	1	0	1	0	0	0
	607	Jalan Masuk Ke Pelabuhan Baru	0	0	0	0	0	0
	608	Jalan Masuk Ke Lapangan Terbang Lama	0	0	0	0	0	0
Penampang	01	Jalan Kota Kinabalu-Sindumin	4	4	8	0	0	0
	500	Jalan Kota Kinabalu-Keningau-Tenom	4	0	4	0	0	0
	501	Jalan Kota Kinabalu-Penampong-Lok Kawi	1	0	1	0	0	0
Papar	01	Jalan Kota Kinabalu-Sindumin	10	0	10	1	0	1
Ranau	22	Jalan Kota Kinabalu-Sandakan	8	3	11	8	3	11
Tambunan	500	Jalan Kota Kinabalu-Keningau-Tenom	4	2	6	0	0	0
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	9	0	9	2	0	2
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	5	0	5	0	0	0
Beaufort	01	Jalan Kota Kinabalu-Sindumin	9	0	9	7	0	7
	502	Jalan Beaufort-Menumbok	4	4	8	4	0	4
Sipitang	01	Jalan Kota Kinabalu-Sindumin	2	0	2	2	0	2
Kuala Penyu	502	Jalan Beaufort-Menumbok	0	0	0	0	0	0
TOTAL			101	29	130	29	3	32

LINTASAN RESOURCES SDN. BHD.

PROVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : July 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	9	4	13	-	-	-
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	9	4	13	-	-	-
3	Kudat	01	Jalan Kota Kinabalu - Kudat	2	2	4	-	-	-
TOTAL :				20	10	30	-	-	-

LINTASAN RESOURCES SDN. BHD.

PROJECTS DIVISION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month: July 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	9	4	13	5	-	5
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	6	1	7	-	-	-
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	-	-	-	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	2	1	3	-	-	-
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	1	-	1	-	-	-
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	-	-	-	-	-	-
TOTAL :				18	6	24	5	-	5

LINTASAN RESOURCES SDN. BHD.

PROVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - BRIDGES

Month : JULY 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Tambunan	500	Jalan Kota Kinabalu - Keningau - Tenom	4	2	6	-	-	-
2	Keningau	500	Jalan Kota Kinabalu - Keningau - Tenom	9	-	9	2	-	2
3	Tenom	500	Jalan Kota Kinabalu - Keningau - Tenom	5	-	5	-	-	-
TOTAL :				18	2	20	2	-	2