

# R05

(BRIDGE AND CULVERT)

LINTASAN RESOURCES SDN. BHD.  
 PROJECTS DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

SUMMARY - CULVERT CLEARING

Month : May 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	46	29	75	3	-	3	1	1	2
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	25	-	25	18	-	18	4	-	4
3	Kudat	01	Jalan Kota Kinabalu - Kudat	53	20	73	21	10	31	1	-	1
<b>TOTAL :</b>				<b>124</b>	<b>49</b>	<b>173</b>	<b>42</b>	<b>10</b>	<b>52</b>	<b>6</b>	<b>1</b>	<b>7</b>

**LINTASAN RESOURCES SDN. BHD.**

*INFRASTRUCTURE OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - CULVERT CLEARING**

Month : May 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous	Current	Cumm.	Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	103	13	116	19	1	20	8	-	8
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	45	37	82	-	2	2	-	-	-
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	56	20	76	3	-	3	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	68	-	68	3	-	3	2	-	2
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	43	-	43	5	-	5	1	-	1
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	-	-	-	-	-	-	-	-	-
<b>TOTAL :</b>				<b>315</b>	<b>70</b>	<b>385</b>	<b>30</b>	<b>3</b>	<b>33</b>	<b>11</b>	<b>-</b>	<b>11</b>

LINTASAN RESOURCES SDN. BHD.  
 PROJECTS DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE

**SUMMARY - CULVERT CLEARING**

Month : May 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	13	-	13	5	-	5	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	20	-	20	-	-	-	4	-	4
3	Papar	01	Jalan Kota Kinabalu - Sindumin	106	-	106	51	-	51	14	-	14
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	6	6	12	-	-	-	-	-	-
5	Kota Kinabalu	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	2	-	2	2	-	2	-	-	-
6	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	27	17	44	-	3	3	-	-	-
7	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	6	-	6	1	-	1	-	-	-
<b>TOTAL :</b>				<b>180</b>	<b>23</b>	<b>203</b>	<b>59</b>	<b>3</b>	<b>62</b>	<b>18</b>	<b>-</b>	<b>18</b>

LINTASAN RESOURCES SDN. BHD.  
 PROJECTS DIVISION OF WEST COAST STATE FEDERAL ROADS MAINTENANCE

**SUMMARY - CULVERT CLEARING**

Month : MAY 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Single Cell			Twin Cell			Multi Cell		
				Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)	Previous (No.)	Current (No.)	Cumm. (No.)
1	Tambunan	500	Jalan Kota Kinabalu - Keningau - Tenom	147	-	147	17	-	17	5	-	5
2	Keningau	500	Jalan Kota Kinabalu - Keningau - Tenom	35	30	65	5	4	9	1	1	2
3	Tenom	500	Jalan Kota Kinabalu - Keningau - Tenom	38	-	38	8	-	8	4	-	4
<b>TOTAL :</b>				<b>220</b>	<b>30</b>	<b>250</b>	<b>30</b>	<b>4</b>	<b>34</b>	<b>10</b>	<b>1</b>	<b>11</b>

**LINTASAN RESOURCES SDN. BHD.**  
**BRIDGES**  
**GRAND SUMMARY**

MONTH:   MAY 2006  

DISTRICT	ROUTE NO.	ROAD NAME	General Cleaning			Painting		
			Previous	Current	Cumm.	Previous	Current	Cumm.
			(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
Kota Belud	01	Jalan Kota Kinabalu-Kudat	2	1	3	0	0	0
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	9	0	9	0	0	0
Kudat	01	Jalan Kota Kinabalu-Kudat	2	0	2	0	0	0
Tuaran	01	Jalan Kota Kinabalu-Kudat	1	0	1	0	0	0
	22	Jalan Kota Kinabalu-Sandakan	0	0	0	0	0	0
	503	Jalan Berungis-Kota Belud	2	0	2	0	0	0
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	8	1	9	0	5	5
	01	Jalan Kota Kinabalu-Sindumin	0	0	0	0	0	0
	501	Jalan Kota Kinabalu-Penampong-Lok Kawi	3	0	3	0	0	0
	606	Jalan Susur Sepangar Bay	1	0	1	0	0	0
	607	Jalan Masuk Ke Pelabuhan Baru	0	0	0	0	0	0
	608	Jalan Masuk Ke Lapangan Terbang Lama	0	0	0	0	0	0
Penampang	01	Jalan Kota Kinabalu-Sindumin	4	0	4	0	0	0
	500	Jalan Kota Kinabalu-Keningau-Tenom	2	2	4	0	0	0
	501	Jalan Kota Kinabalu-Penampong-Lok Kawi	0	1	1	0	0	0
Papar	01	Jalan Kota Kinabalu-Sindumin	10	0	10	1	0	1
Ranau	22	Jalan Kota Kinabalu-Sandakan	4	1	5	4	1	5
Tambunam	500	Jalan Kota Kinabalu-Keningau-Tenom	4	0	4	0	0	0
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	3	3	6	2	0	2
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	5	0	5	0	0	0
Beaufort	01	Jalan Kota Kinabalu-Sindumin	7	1	8	6	1	7
	502	Jalan Beaufort-Menumbok	4	0	4	4	0	4
Sipitang	01	Jalan Kota Kinabalu-Sindumin	0	1	1	0	1	1
Kuala Penyu	502	Jalan Beaufort-Menumbok	0	0	0	0	0	0
<b>TOTAL</b>			<b>71</b>	<b>11</b>	<b>82</b>	<b>17</b>	<b>8</b>	<b>25</b>

**LINTASAN RESOURCES SDN. BHD.**

*PROVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - BRIDGES**

*Month: May 2006*

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	2	1	3	-	-	-
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	9		9	-	-	-
3	Kudat	01	Jalan Kota Kinabalu - Kudat	2		2	-	-	-
<b>TOTAL :</b>				<b>13</b>	<b>1</b>	<b>14</b>	<b>-</b>	<b>-</b>	<b>-</b>

**LINTASAN RESOURCES SDN. BHD.**

*PROJECTS DIVISION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE*

**SUMMARY - BRIDGES**

Month : May 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	8	1	9	-	5	5
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	1	-	1	-	-	-
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	-	-	-	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	2	-	2	-	-	-
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	1	-	1	-	-	-
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	-	-	-	-	-	-
<b>TOTAL :</b>				<b>12</b>	<b>1</b>	<b>13</b>	<b>-</b>	<b>5</b>	<b>5</b>

**LINTASAN RESOURCES SDN. BHD.**

*PROVIDER OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE*

**SUMMARY - BRIDGES**

Month : May 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	4	-	4	-	-	-
3	Papar	01	Jalan Kota Kinabalu - Sindumin	10	-	10	1	-	1
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	2	2	4	-	-	-
5	Kota Kinabalu	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	3	-	3	-	-	-
6	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	-	1	1	-	-	-
7	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	-	-	-	-	-	-
<b>TOTAL :</b>				<b>19</b>	<b>3</b>	<b>22</b>	<b>1</b>	<b>-</b>	<b>1</b>

**LINTASAN RESOURCES SDN. BHD.**

*PROVIDER OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - BRIDGES**

Month : MAY 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	General Maintenance			Painting		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(No.)	(No.)	(No.)	(No.)	(No.)	(No.)
1	Tambunan	500	Jalan Kota Kinabalu - Keningau - Tenom	4	-	4	-	-	-
2	Keningau	500	Jalan Kota Kinabalu - Keningau - Tenom	3	3	6	2	-	2
3	Tenom	500	Jalan Kota Kinabalu - Keningau - Tenom	5	-	5	-	-	-
<b>TOTAL :</b>				<b>12</b>	<b>3</b>	<b>15</b>	<b>2</b>	<b>-</b>	<b>2</b>