

**PENSWASTAAN PENYENGGARAAN
JALAN-JALAN PERSEKUTUAN DI SABAH
(PANTAI BARAT & PENDALAMAN)**



THE GOVERNMENT OF MALAYSIA

**LAPORAN KEMAJUAN BULANAN
No. 5**

JANUARI 2004



Jabatan Kerja Raya, Negeri Sabah

Kontraktor : Lintasan Resources Sdn. Bhd. 566483-H

R 02

**PENYENGGARAAN
BAHU JALAN
(SHOULDER)**

R02 SHOULDER REPAIR

Film Batch No: 0514/11



BEFORE

Film Batch No: 0514/12



IN PROGRESS

Film Batch No: 0564/8



AFTER

DISTRICT : KENINGAU

ROUTE NO. : 500 JALAN KK-KGU-TENOM LOCATION (by Km post)

: Km123.400

R02: ROAD SHOULDER

FILM BATCH NO:4598/6



BEFORE

FILM BATCH NO:44598/8



IN PROGRESS

FILM BATCH NO:44598/9



AFTER

LINTASAN RESOURCES SDN BHD (566483-H)
PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR RECORD

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m ²)	GRAVEL SHOULDER AREA (m ²)
1	Ranau	22	Jalan Kota Kinabalu - Sandakan	-	163.40
TOTAL				-	163.40

Checked & Certified Correct By :

Checked & Certified Correct By :

For Lintasan Resources Sdn Bhd

For Jabatan Kerja Raya

R02 ROAD SHOULDER

FILM BATCH NO:3921/09



BEFORE

FILM BATCH NO:3921/10



IN PROGRESS

FILM BATCH NO:3921/11



AFTER

R02 SHOULDER

FILM BATCH NO: 3697/13



BEFORE

FILM BATCH NO: 3697/14



IN PROGRESS

FILM BATCH NO: 3697/19



AFTER

DISTRICT : BEAUFORT
ROUTE NO. : 01 JALAN KOTA KINABALU-SINDUMIN LOCATION : KM107.930

(B) ROUTINE INSPECTION

FILM BATCH NO.:3906/11



BEFORE

FILM BATCH NO.:3906/12



AFTER