

R 02

**PENYENGGARAAN
BAHU JALAN
(SHOULDER)**

DISTRICT : TAMBUNAN
ROUTE NO : 500 JALAN KOTA KINABALU-KENINGAU-TENOM
LOCATION : CH155.850 (LHS)

R02 ROAD SHOULDER



Film Batch No: R02-2210-92

BEFORE



Film Batch No: R07-1109-11

IN PROGRESS



Film Batch No: R07-1109-12

AFTER

**SHOULDER REPAIR
GRAND SUMMARY**

MONTH: OCTOBER 2004

R02 - SHOULDER REPAIR								
DISTRICT	ROUTE NO	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER		
			Previous	Current	Cumm.	Previous	Current	Cumm.
			(m ²)	(m ²)	(m ²)	(m ²)	(m ²)	(m ²)
Kota Belud	01	Jalan Kota Kinabalu-Kudat	188 81	300 00	488 81	405 42	-	405 42
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	-	-	-	-	-	-
Kudat	01	Jalan Kota Kinabalu-Kudat	-	-	-	300 00	-	300 00
Tuaran	01	Jalan Kota Kinabalu-Kudat	60 00	-	60 00	1,520 00	-	1,520 00
	22	Jalan Kota Kinabalu-Sandakan	-	390 00	390 00	-	-	-
	503	Jalan Berungis-Kota Belud	-	-	-	-	-	-
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	1,831 00	-	1,831 00	20,941 18	-	20,941 18
	01	Jalan Kota Kinabalu-Sindumin	-	-	-	75 75	-	75 75
	606	Jalan Susur Sepangar Bay	-	-	-	-	-	-
	607	Jalan Masuk Ke Pelabuhan Baru	-	-	-	-	-	-
	608	Jalan Masuk ke Lapangan Terbang Lama	-	-	-	-	-	-
Penampang	01	Jalan Kota Kinabalu-Sindumin	8,463 00	-	8,463 00	3,540 00	-	3,540 00
	500	Jalan Kota Kinabalu-Keningau-Tenom	3,190 00	-	3,190 00	11,217 77	-	11,217 77
	501	Jalan Kota Kinabalu-Penampang-Lokkawı	-	-	-	8,120 13	-	8,120 13
Papar	01	Jalan Kota Kinabalu-Sindumin	6,895 00	-	6,895 00	207 27	-	207 27
Ranau	22	Jalan Kota Kinabalu-Sandakan	1,934 90	75 50	2,010 40	1,338 73	460 50	1,799 23
Tambunan	500	Jalan Kota Kinabalu-Keningau-Tenom	5,771 19	802 00	6,573 19	2,126 43	-	2,126 43
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	-	-	-	862 09	-	862 09
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	-	-	-	88 20	-	88 20
Beaufort	01	Jalan Kota Kinabalu-Sindumin	27 00	-	27 00	1,543 24	4,409 10	5,952 34
	502	Jalan Beaufort-Menumbok	175 00	-	175 00	96 60	-	96 60
Sipitang	01	Jalan Kota Kinabalu-Sindumin	-	-	-	40 39	-	40 39
Kuala Penyu	502	Jalan Beaufort-Menumbok	-	-	-	119 70	-	119 70
TOTAL			28,535.90	1,567.50	30,103.40	52,542.90	4,869.60	57,412.50

LINTASAN RESOURCES SDN BHD (566483-H)
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY

Ending Period : 31 October 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m ²)		GRAVEL SHOULDER AREA (m ²)		GRASS INVENTORY		ROAD SHOULDER DEFECT (m ²)
				PREVIOUS MONTH	CURRENT MONTH	PREVIOUS MONTH	CURRENT MONTH	EARTH SHOULDER ESTIMATE QTY (m ²)	GRAVEL SHOULDER ESTIMATE QTY (m ²)	
WEST COAST (NORTH)										
1	KOTA BELUD	01	Jalan Kota Kinabalu - Kudat	188 81	300 00	405 42	-	325,804 50	1,225 40	23,342 70
2	KOTA MARUDU	01	Jalan Kota Kinabalu - Kudat					184,545 00	14,474 50	18,724 48
3	KUDAT	01	Jalan Kota Kinabalu - Kudat			300 00	-	313,817 50	5,445 60	911 00
TOTAL				188.81	300.00	705.42	-	824,167.00	21,145.50	42,978.18

LINTASAN RESOURCES SDN BID (566483-H)
PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY

Ending Period : 31st October 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m ²)		GRAVEL SHOULDER AREA (m ²)	
				PREVIOUS MONTH	CURRENT MONTH	PREVIOUS MONTH	CURRENT MONTH
WEST COAST (NORTH)							
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	1,831.00	-	20,941.18	-
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	60.00	-	1,520.00	-
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	-	390.00	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	-	-	-	-
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	-	-	-	-
6	Kota Kinabalu	607	Jalan Masuk ke Pelabuhan Baru, KK	-	-	-	-
TOTAL				1,891.00	390.00	22,461.18	-
WEST COAST (SOUTH)							
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	-	-	75.75	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	8,463.00	-	3,540.00	-
3	Papar	01	Jalan Kota Kinabalu - Sindumin	6,895.00	-	207.27	-
4	Penampang	500	Jalan KK - Keningau - Tenom	3,190.00	-	11,217.77	-
5	Penampang	501	Jalan KK - Penampang - Lok Kawi	-	-	8,120.13	-
6	Kota Kinabalu	608	Jalan Masuk ke Lapangan Terbang Lama, KK	-	-	-	-
TOTAL				18,548.00	-	23,160.92	-
TOTAL FOR (NORTH + SOUTH) =				20,439.00	390.00	45,622.10	0.00

LINTASAN RESOURCES SDN BHD (566483-H)
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY

Ending Period : 30TH OCTOBER 2004

ITEM	DISTRICT	ROUTE NO	ROADNAME	EARTH SHOULDER AREA (m2)			GRAVEL SHOULDER AREA (m2)			INVENTORY		ROAD SHOULDER SHOULDER DEFECTS (M2)
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	EARTH SHOULDER EXTIMATE QTY (m2)	GRAVEL SHOULDER EXTIMATE QTY (m2)	
1	Tambunan	500	Jalan K K - Keningau - Tenom	5771 19	802 00 0 00	6573 19	2126 43	0 00	2126 43	187,150 00	143545	41,772 50
2	Keningau	500	Jalan K K - Keningau - Tenom	0 00	0 00	0 00	862 09	0 00	862 09	67,600 00	114,620 00	18,785 70
3	Tenom	500	Jalan K K - Keningau - Tenom	0 00	0 00	0 00	88 20	0 00	88 20	50,750 00	117 000 00	8 808 44
TOTAL				5,771.19	802.0	6,573.19	3,076.7	-	3,076.7	305,500.00	375,165.00	69,366.64

LINTASAN RESOURCES SDN BHD (566483-II)
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR RECORD

Ending Period : 31th OCTOBER 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	AREA (m ²) - Earth Shoulder		AREA (m ²) - Gravel Shoulder	
				PREVIOUS MONTH	CURRENT MONTH	PREVIOUS MONTH	CURRENT MONTH
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	27.00	0.00	1543.24	4409.10
2	Beaufort	502	Jalan Beaufort-Menumbok	175.00	0.00	96.60	0.00
3	Sipitang	01	Jalan Kota Kinabalu - Sindumin	0.00	0.00	40.39	0.00
4	Kuala Penyu	502	Jalan Beaufort-Menumbok	0.00	0.00	119.70	0.00
TOTAL				202.00	-	1,799.93	4,409.10
							6,209.03