

**R 02**

**PENYENGGARAAN  
BAHU JALAN  
(SHOULDER)**

DISTRICT : KOTA BELUD  
ROUTE NO : 01-JALAN KOTA KINABALU-KUDAT  
LOCATION : CH 79.530

### R02 SHOULDER



Film Batch No: PC030218

**BEFORE**



Film Batch No: PC030227

**IN PROGRESS**



Film Batch No: PC030230

**AFTER**

DISTRICT : PENAMPANG  
ROUTE NO : 500 KK-KENINGAU-TENOM  
LOCATION : KM19.850 (RHS)

### R02 SHOULDER



Picture No: 11124/038

**BEFORE**



Picture No: 27124/009

**IN PROGRESS**



Picture No: 18124/011

**AFTER**


DISTRICT : PENAMPANG  
ROUTE NO : 500 KK-KENINGAU-TENOM  
LOCATION : KM36.500 (LHS)

### R02 SHOULDER



Picture No: 16124/013

**BEFORE**



Picture No: 22124/006

**IN PROGRESS**



Picture No: 22124/007

**AFTER**

DISTRICT : PENAMPANG  
ROUTE NO : 500 KK-KENINGAU-TENOM  
LOCATION : KM37.80 (LHS)

### R02 SHOULDER



Picture No: 16124/005

### BEFORE



Picture No: 27124/001

### IN PROGRESS



Picture No: 18124/005

### AFTER

DISTRICT : KENINGAU  
ROUTE NO : 500 JALAN KOTA KINABALU-KENINGAU-TENOM  
LOCATION : CH114.200 - RHS

**R02 ROAD SHOULDER**



Film Batch No: R02-1204-04

**BEFORE**



Film Batch No: R02-1204-05

**IN PROGRESS**



Film Batch No: R02-1204-06

**AFTER**

LINTASAN RESOURCES SDN. BHD.  
**SHOULDER REPAIR**  
**GRAND SUMMARY**

MONTH: DECEMBER 2004

<b>R02 - SHOULDER REPAIR</b>								
DISTRICT	ROUTE NO	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER		
			Previous	Current	Cumm.	Previous	Current	Cumm.
			(m <sup>2</sup> )	(m <sup>2</sup> )	(m <sup>2</sup> )	(m <sup>2</sup> )	(m <sup>2</sup> )	(m <sup>2</sup> )
Kota Belud	01	Jalan Kota Kinabalu-Kudat	2,288.81	6,500.00	8,788.81	405.42	-	405.42
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	-	-	-	-	-	-
Kudat	01	Jalan Kota Kinabalu-Kudat	-	-	-	300.00	-	300.00
Tuaran	01	Jalan Kota Kinabalu-Kudat	60.00	-	60.00	1,520.00	-	1,520.00
	22	Jalan Kota Kinabalu-Sandakan	390.00	-	390.00	-	-	-
	503	Jalan Berungis-Kota Belud	-	-	-	-	-	-
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	4,760.90	-	4,760.90	21,618.78	-	21,618.78
	01	Jalan Kota Kinabalu-Sindumin	-	-	-	75.75	-	75.75
	606	Jalan Susur Sepangar Bay	-	-	-	-	-	-
	607	Jalan Masuk Ke Pelabuhan Baru	-	-	-	-	-	-
	608	Jalan Masuk ke Lapangan Terbang Lama	-	-	-	-	-	-
Penampang	01	Jalan Kota Kinabalu-Sindumin	9,313.00	-	9,313.00	7,014.00	-	7,014.00
	500	Jalan Kota Kinabalu-Keningau-Tenom	11,611.25	1,930.84	13,542.09	11,888.17	4,632.55	16,520.72
	501	Jalan Kota Kinabalu-Penampang-Lokkawi	467.50	-	467.50	9,333.63	-	9,333.63
Papar	01	Jalan Kota Kinabalu-Sindumin	9,595.00	-	9,595.00	207.27	-	207.27
Ranau	22	Jalan Kota Kinabalu-Sandakan	2,718.40	603.50	3,321.90	1,799.23	-	1,799.23
Tambunan	500	Jalan Kota Kinabalu-Keningau-Tenom	6,573.19	-	6,573.19	2,126.43	-	2,126.43
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	-	1,650.00	1,650.00	862.09	8,646.00	9,508.09
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	-	-	-	88.20	-	88.20
Beaufort	01	Jalan Kota Kinabalu-Sindumin	389.70	-	389.70	5,952.34	-	5,952.34
	502	Jalan Beaufort-Menumbok	175.00	-	175.00	96.60	-	96.60
Sipitang	01	Jalan Kota Kinabalu-Sindumin	-	-	-	40.39	-	40.39
Kuala Penyu	502	Jalan Beaufort-Menumbok	-	-	-	119.70	-	119.70
<b>TOTAL</b>			<b>48,342.75</b>	<b>10,684.34</b>	<b>59,027.09</b>	<b>63,448.00</b>	<b>13,278.55</b>	<b>76,726.55</b>

**LINTASAN RESOURCES SDN BHD** (566483-H)  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY

Ending Period : 31 December 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m <sup>2</sup> )			GRAVEL SHOULDER AREA (m <sup>2</sup> )			GRASS INVENTORY		ROAD SHOULDER DEFECT (m <sup>2</sup> )
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	EARTH SHOULDER ESTIMATE QTY (m <sup>2</sup> )	GRAVEL SHOULDER ESTIMATE QTY (m <sup>2</sup> )	
			<b><u>WEST COAST (NORTH)</u></b>									
1	KOTA BELUD	01	Jalan Kota Kinabalu - Kudat	2,288.81	6,500.00	8,788.81	405.42	-	405.42	325,804.50	1,225.40	23,342.70
2	KOTA MARUDU	01	Jalan Kota Kinabalu - Kudat							184,545.00	14,474.50	18,724.48
3	KUDAT	01	Jalan Kota Kinabalu - Kudat				300.00	-	300.00	313,817.50	5,445.60	911.00
<b>TOTAL</b>				<b>2,288.81</b>	<b>6,500.00</b>	<b>8,788.81</b>	<b>705.42</b>	<b>-</b>	<b>705.42</b>	<b>824,167.00</b>	<b>21,145.50</b>	<b>42,978.18</b>

# LINTASAN RESOURCES SDN BHD (566483-H)

## PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

### SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY

Ending Period : 31st December 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA ( m <sup>2</sup> )			GRAVEL SHOULDER AREA ( m <sup>2</sup> )		
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH
<b>WEST COAST (NORTH)</b>									
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	4,760.90	-	4,760.90	21,618.78	-	21,618.78
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	60.00	-	60.00	1,520.00	-	1,520.00
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	390.00	-	390.00	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	-	-	-	-	-	-
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	-	-	-	-	-	-
6	Kota Kinabalu	607	Jalan Masuk ke Pelabuhan Baru, KK	-	-	-	-	-	-
<b>TOTAL</b>				<b>5,210.90</b>	<b>-</b>	<b>5,210.90</b>	<b>23,138.78</b>	<b>-</b>	<b>23,138.78</b>

**LINTASAN RESOURCES SDN BHD** (566483-H)  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY FOR R02 - SHOULDER REPAIR RECORD

Ending Period : 31st December 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER - AREA ( m <sup>2</sup> )		GRAVEL SHOULDER - AREA (m <sup>2</sup> )	
				PREVIOUS MONTH	CURRENT MONTH	PREVIOUS MONTH	CURRENT MONTH
1	Ranau	22	Jalan Kota Kinabalu - Sandakan	2,718.40	603.50	1,799.23	-
<b>TOTAL</b>				<b>2,718.40</b>	<b>603.50</b>	<b>1,799.23</b>	<b>-</b>
						<b>1,799.23</b>	<b>1,799.23</b>



**LINTASAN RESOURCES SDN BHD** (566483-H)  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY FOR R02 - SHOULDER REPAIR SUMMARY**

**Ending Period : 31st DECEMBER 2004**

ITEM	DISTRICT	ROUTE NO.	ROADNAME	EARTH SHOULDER AREA (m2)			GRAVEL SHOULDER AREA (m2)			INVENTORY		ROAD SHOULDER SHOULDER DEFECTS (M2)
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	EARTH SHOULDER ESTIMATE QTY (m2)	GRAVEL SHOULDER ESTIMATE QTY (m2)	
1	Tambunan	500	Jalan K.K - Keningau - Tenom	6573.19	0.00	6573.19	2126.43	0.00	2126.43	187,150.00	143545	41,772.50
2	Keningau	500	Jalan K.K - Keningau - Tenom	0.00	1650.00	1650.00	862.09	8646.00	9508.09	67,600.00	114,620.00	18,785.70
3	Tenom	500	Jalan K.K - Keningau - Tenom	0.00	0.00	0.00	88.20	0.00	88.20	50,750.00	117,000.00	8,808.44
<b>TOTAL</b>				<b>6,573.19</b>	<b>1,650.0</b>	<b>8,223.19</b>	<b>3,076.72</b>	<b>8,646.00</b>	<b>11,722.72</b>	<b>305,500.00</b>	<b>375,165.00</b>	<b>69,366.64</b>

# LINTASAN RESOURCES SDN BHD (566483-H)

PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

## SUMMARY FOR R02 - SHOULDER REPAIR RECORD

Ending Period : 31st DECEMBER 2004

ITEM	DISTRICT	ROUTE NO.	ROADNAME	AREA ( m <sup>2</sup> ) - Earth Shoulder		AREA ( m <sup>2</sup> ) - Gravel Shoulder	
				PREVIOUS MONTH	CURRENT MONTH	PREVIOUS MONTH	CURRENT MONTH
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	389.70	0.00	5952.34	0.00
2	Beaufort	502	Jalan Beaufort-Menumbok	175.00	0.00	96.60	0.00
3	Sipitang	01	Jalan Kota Kinabalu - Sindumin	0.00	0.00	40.39	0.00
4	Kuala Penyu	502	Jalan Beaufort-Menumbok	0.00	0.00	119.70	0.00
<b>TOTAL</b>				<b>564.70</b>	<b>-</b>	<b>6,209.03</b>	<b>-</b>
						<b>6,209.03</b>	<b>6,209.03</b>