

# RO2

(SHOULDER)

DISTRICT : SIPITANG  
ROUTE NO : 01 JALAN KOTA KINABALU - SINDUMIN  
LOCATION : CH140.187 (KM141.947) - RHS

### **R02 SHOULDER REPAIR**



**BEFORE**



**IN PROGRESS**



**AFTER**

DISTRICT : KOTA KINABALU  
ROUTE NO : 01 JALAN KOTA KINABALU - KUDAT  
LOCATION : KM8.195

### **R02 SHOULDER REPAIR**



**BEFORE**



**IN PROGRESS**



**AFTER**

LINTASAN RESOURCES SDN BHD  
PRIVATISATION OF LABUAN FEDERAL ROADS MAINTENANCE

---

**R02 ~ ROAD SHOULDER.**

**Road Name : Jalan Bukit Kuda**

Route No : L710

Location : KM 2.65 LHS

Date : 18/06/2008

**BEFORE**



Film Batch: L6-13-001

**IN PROGRESS**



Film Batch: L6-13-020

**AFTER**



Film Batch: L7-06-043

LINTASAN RESOURCES SDN. BHD.  
**SHOULDER REPAIR**  
**GRAND SUMMARY**

MONTH:                                                                                                              
JUNE 2008

DISTRICT	ROUTE NO	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
			Previous	Current	Cumm.	Previous		Current		Cumm.	
			Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Vol (m <sup>3</sup> )	Area (m <sup>2</sup> )	Vol (m <sup>3</sup> )	Area (m <sup>2</sup> )	Vol (m <sup>3</sup> )
Kota Belud	01	Jalan Kota Kinabalu-Kudat	115.00	83.00	198.00	0.00	0.00	0.00	0.00	0.00	0.00
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	66.00	0.00	66.00	0.00	0.00	0.00	0.00	0.00	0.00
Kudat	01	Jalan Kota Kinabalu-Kudat	125.00	35.00	160.00	0.00	0.00	0.00	0.00	0.00	0.00
Tuaran	01	Jalan Kota Kinabalu-Kudat	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	22	Jalan Kota Kinabalu-Sandakan	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	503	Jalan Berungis-Kota Belud	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	0.00	0.00	0.00	0.00	0.00	62.16	15.42	62.16	15.42
	01	Jalan Kota Kinabalu-Sindumin	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	606	Jalan Susur Sepangar Bay	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	607	Jalan Masuk Ke Pelabuhan Baru	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	608	Jalan Masuk ke Lapangan Terbang Lama	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Penampang	01	Jalan Kota Kinabalu-Sindumin	8,351.20	10,532.40	18,883.60	890.08	106.75	0.00	0.00	890.08	106.75
	500	Jalan Kota Kinabalu-Keningau-Tenom	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	501	Jalan Kota Kinabalu-Penampang-Lokkawi	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Papar	01	Jalan Kota Kinabalu-Sindumin	60.00	0.00	60.00	38.11	6.86	0.00	0.00	38.11	6.86
Ranau	22	Jalan Kota Kinabalu-Sandakan	1,666.00	599.80	2,265.80	0.00	0.00	0.00	0.00	0.00	0.00
Tambunan	500	Jalan Kota Kinabalu-Keningau-Tenom	1,121.70	0.00	1,121.70	123.00	20.12	0.00	0.00	123.00	20.12
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	53.90	11.70	65.60	0.00	0.00	13.50	1.01	13.50	1.01
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	22.20	0.00	22.20	0.00	0.00	0.00	0.00	0.00	0.00
Beaufort	01	Jalan Kota Kinabalu-Sindumin	2,431.40	34.65	2,466.05	0.00	0.00	0.00	0.00	0.00	0.00
	502	Jalan Beaufort-Menumbok	14.60	0.00	14.60	0.00	0.00	0.00	0.00	0.00	0.00
Sipitang	01	Jalan Kota Kinabalu-Sindumin	16.80	14.40	31.20	0.00	0.00	0.00	0.00	0.00	0.00
Kuala Penyu	502	Jalan Beaufort-Menumbok	35.40	0.00	35.40	0.00	0.00	0.00	0.00	0.00	0.00
<b>TO TAL</b>			14,079.20	11,310.95	25,390.15	1,051.19	133.73	75.66	16.43	1,126.85	150.16

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

*Month : JUNE 2008*

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	2,431.40	34.65	2,466.05	-	-	-	-	-	-
2	Beaufort	502	Jalan Beaufort - Menumbok	14.60	-	14.60	-	-	-	-	-	-
3	Sipitang	01	Jalan Kota Kinabalu - Sindumin	16.80	14.40	31.20	-	-	-	-	-	-
4	Kuala Penyu	502	Jalan Beaufort - Menumbok	35.40	-	35.40	-	-	-	-	-	-
<b>TOTAL</b>				<b>2,498.20</b>	<b>49.05</b>	<b>2,547.25</b>	-	-	-	-	-	-

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** BEAUFORT

**ROUTE NO.** 01

**ROAD NAME:** JALAN KOTA KINABALU - SINDUMIN

**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m <sup>2</sup> )	Length (m)	Width (m)	Depth (m)	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	<b>2,431.40</b>	-	-	-	<b>0.00</b>	<b>0.00</b>	-
1	21/06/2008	73.080	73.083	3.00	0.85	0.100	2.55						LHS
2	21/06/2008	78.570	78.573	3.00	0.35	0.080	1.05						LHS
3	21/06/2008	78.575	78.577	2.00	0.30	0.080	0.60						LHS
4	21/06/2008	78.560	78.563	3.00	0.40	0.080	1.20						RHS
5	21/06/2008	78.580	78.582	2.00	0.30	0.080	0.60						LHS
6	21/06/2008	80.050	80.052	2.00	0.50	0.100	1.00						LHS
7	21/06/2008	80.055	80.058	3.00	0.55	0.090	1.65						RHS
8	21/06/2008	80.775	80.777	2.00	0.30	0.100	0.60						RHS
9	21/06/2008	80.780	80.782	2.00	0.50	0.110	1.00						RHS
10	23/06/2008	125.790	125.792	2.00	1.00	0.120	2.00						LHS
11	23/06/2008	125.807	125.811	4.00	3.00	0.100	12.00						LHS
12	23/06/2008	125.815	125.819	4.00	2.60	0.100	10.40						LHS
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>CARRIED FORWARD:</b>							<b>2,466.05</b>				<b>0.00</b>	<b>0.00</b>	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

DISTRICT: SIPITANG  
 ROUTE NO. 01  
 ROAD NAME: JALAN KOTA KINABALU - SINDUMIN  
 MONTH: JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	16.80	-	-	-	0.00	0.00	-
1	23/06/2008	140.187	140.190	3.00	2.50	0.080	7.50						RHS
2	23/06/2008	140.190	140.193	3.00	2.30	0.090	6.90						RHS
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>CARRIED FORWARD:</b>							31.20				0.00	0.00	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** BEAUFORT

**ROUTE NO.** 502

**ROAD NAME:** JALAN BEAUFORT - MENUMBOK

**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS	
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume		
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )		
<b>BROUGHT FORWARD:</b>				-	-	-	14.60	-	-	-	0.00	0.00	-	
1														
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
<b>CARRIED FORWARD:</b>							14.60				0.00	0.00		

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KUALA PENYU  
**ROUTE NO.** 502  
**ROAD NAME:** JALAN BEAUFORT - MENUMBOK  
**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS	
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume		
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )		
<b>BROUGHT FORWARD:</b>				-	-	-	35.40	-	-	-	0.00	0.00	-	
1														
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
<b>CARRIED FORWARD:</b>							35.40				0.00	0.00		

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY - SHOULDER REPAIR RECORD**

Month : JUNE 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	TAMBUNAN	500	Jalan Kota Kinabalu - Keningau - Tenom	1,121.70	-	1,121.70	123.30	20.12	-	-	123.30	20.12
2	KENINGAU	500	Jalan Kota Kinabalu - Keningau - Tenom	53.90	11.70	65.60	-	-	13.50	1.01	13.50	1.01
3	TENOM	500	Jalan Kota Kinabalu - Keningau - Tenom	22.20	-	22.20	-	-	-	-	-	-
<b>TOTAL</b>				<b>1,197.80</b>	<b>11.70</b>	<b>1,209.50</b>	<b>123.30</b>	<b>20.12</b>	<b>13.50</b>	<b>1.01</b>	<b>136.80</b>	<b>21.13</b>

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** TAMBUNAN  
**ROUTE NO.** 500  
**ROAD NAME:** JLN K. KINABALU - KENINGAU - TENOM  
**MONTH:** June 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS	
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume		
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )		
<b>BROUGHT FORWARD:</b>							1,121.70				123.30	20.12		
1														
2														
3														
4														
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
<b>TOTAL</b>							1,121.70				123.30	20.12		

**LINTASAN RESOURCES SDN. BHD.**

MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KENINGAU  
**ROUTE NO.** 500  
**ROAD NAME:** JLN K. KINABALU - KENINGAU - TENOM  
**MONTH:** June 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>							<b>53.90</b>				<b>0.00</b>	<b>0.00</b>	
1	6/21/2008	115.400	115.403	3.00	1.50	0.075	4.50						RHS
2	6/25/2008	104.550	104.553	3.00	2.40	0.075	7.20						RHS
3	6/25/2008	119.550	119.555					5.00	2.70	0.08	13.5	1.01	LHS
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>TOTAL</b>							<b>65.60</b>				<b>13.50</b>	<b>1.01</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** TENOM

**ROUTE NO.** 500

**ROAD NAME:** JLN K. KINABALU - KENINGAU - TENOM

**MONTH:** June 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>							22.20				0.00	0.00	
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>TOTAL</b>							22.20				0.00	0.00	

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

*Month: June 2008*

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	-	-	-	-	-	62.16	15.42	62.16	15.42
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	-	-	-	-	-	-	-	-	-
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	-	-	-	-	-	-	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	-	-	-	-	-	-	-	-	-
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	-	-	-	-	-	-	-	-	-
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	-	-	-	-	-	-	-	-	-
<b>TOTAL</b>				-	-	-	-	-	<b>62.16</b>	<b>15.42</b>	<b>62.16</b>	<b>15.42</b>

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KOTA KINABALU  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD:</b>				-	-	-	-	-	-	-	-	-	
1	16/06/2008	16.140	16.151	-	-	-	-	11.20	1.30	0.250	14.56	3.64	RHS
2	16/06/2008	8.206	8.208	-	-	-	-	1.50	1.10	0.175	1.65	0.29	RHS
3	16/06/2008	8.195	8.198	-	-	-	-	3.00	1.30	0.250	3.90	0.98	RHS
4	16/06/2008	8.194	8.196	-	-	-	-	2.00	1.30	0.250	2.60	0.65	RHS
5	16/06/2008	8.190	8.192	-	-	-	-	2.00	0.70	0.250	1.40	0.35	RHS
6	16/06/2008	8.185	8.190	-	-	-	-	4.80	1.80	0.250	8.64	2.16	RHS
7	16/06/2008	7.680	7.683	-	-	-	-	3.40	1.60	0.250	5.44	1.36	LHS
8	16/06/2008	7.680	7.682	-	-	-	-	1.70	1.30	0.250	2.21	0.55	LHS
9	16/06/2008	7.690	7.690	-	-	-	-	2.70	1.50	0.250	4.05	1.01	LHS
10	16/06/2008	7.695	7.695	-	-	-	-	3.70	1.50	0.250	5.55	1.39	LHS
11	16/06/2008	15.355	15.355	-	-	-	-	7.60	1.60	0.250	12.16	3.04	LHS
<b>TOTAL :</b>							-				<b>62.16</b>	<b>15.42</b>	

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

Month: June 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	8,351.20	10,532.40	18,883.60	890.08	106.75	-	-	890.08	106.75
3	Papar	01	Jalan Kota Kinabalu - Sindumin	60.00	-	60.00	38.11	6.86	-	-	38.11	6.86
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	-	-	-	-	-	-	-	-	-
5	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	-	-	-	-	-	-	-	-	-
6	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	-	-	-	-	-	-	-	-	-
<b>TOTAL</b>				<b>8,411.20</b>	<b>10,532.40</b>	<b>18,943.60</b>	<b>928.19</b>	<b>113.61</b>	<b>-</b>	<b>-</b>	<b>928.19</b>	<b>113.61</b>

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 01

**ROAD NAME:** JALAN KOTA KINABALU-SINDUMIN

**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
<b>BROUGHT FORWARD:</b>							<b>8,351.20</b>				<b>890.08</b>	<b>106.75</b>	
1	02/06/08	7.440	7.528	88.00	3.40		299.20				0.00	0.00	RHS
2	02/06/08	7.567	7.685	118.00	3.80		448.40				0.00	0.00	RHS
3	02/06/08	7.751	7.812	61.00	2.70		164.70				0.00	0.00	RHS
4	02/06/08	7.867	7.882	15.00	1.10		16.50				0.00	0.00	RHS
5	02/06/08	7.882	7.944	62.00	4.00		248.00				0.00	0.00	RHS
6	02/06/08	7.960	8.015	55.00	3.80		209.00				0.00	0.00	RHS
7	02/06/08	8.015	8.035	20.00	2.00		40.00				0.00	0.00	RHS
8	02/06/08	8.035	8.094	59.00	4.00		236.00				0.00	0.00	RHS
9	02/06/08	8.186	8.293	107.00	3.80		406.60				0.00	0.00	RHS
10	02/06/08	8.293	8.303	10.00	3.80		38.00				0.00	0.00	RHS
11	02/06/08	8.303	8.335	32.00	1.80		57.60				0.00	0.00	RHS
12	02/06/08	8.335	8.345	10.00	1.80		18.00				0.00	0.00	RHS
13	02/06/08	8.345	8.411	66.00	3.60		237.60				0.00	0.00	RHS
14	02/06/08	8.411	8.431	20.00	3.60		72.00				0.00	0.00	RHS
15	02/06/08	8.431	8.609	178.00	4.50		801.00				0.00	0.00	RHS
16	02/06/08	8.619	8.733	114.00	4.00		456.00				0.00	0.00	RHS
17	02/06/08	8.733	8.746	13.00	1.30		16.90				0.00	0.00	RHS
18	02/06/08	8.746	8.760	14.00	3.70		51.80				0.00	0.00	RHS
19	02/06/08	8.847	8.952	105.00	5.00		525.00				0.00	0.00	RHS
20	02/06/08	9.224	9.307	83.00	3.60		298.80				0.00	0.00	RHS
21	03/06/08	7.403	7.435	32.00	1.00		32.00				0.00	0.00	LHS
22	03/06/08	7.435	7.472	37.00	4.70		173.90				0.00	0.00	LHS
23	03/06/08	7.481	7.607	126.00	2.80		352.80				0.00	0.00	LHS
24	03/06/08	7.607	7.616	9.00	2.80		25.20				0.00	0.00	LHS
25	03/06/08	7.616	7.676	60.00	3.80		228.00				0.00	0.00	LHS
26	03/06/08	7.676	7.682	6.00	3.80		22.80				0.00	0.00	LHS
27	03/06/08	7.682	7.723	41.00	3.30		135.30				0.00	0.00	LHS
28	03/06/08	7.723	7.732	9.00	2.40		21.60				0.00	0.00	LHS
29	03/06/08	7.732	7.764	32.00	2.10		67.20				0.00	0.00	LHS
30	03/06/08	7.825	7.942	117.00	2.10		245.70				0.00	0.00	LHS
<b>CARRIED FORWARD:</b>							<b>14,296.80</b>				<b>890.08</b>	<b>106.75</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PENAMPANG

**ROUTE NO.:** 01

**ROAD NAME:** JALAN KOTA KINABALU-SINDUMIN

**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
<b>BROUGHT FORWARD:</b>							<b>14,296.80</b>				<b>890.08</b>	<b>106.75</b>	
31	03/06/08	7.942	7.949	7.00	3.00		21.00				0.00	0.00	LHS
32	03/06/08	7.949	7.991	42.00	3.00		126.00				0.00	0.00	LHS
33	03/06/08	7.991	7.998	7.00	3.50		24.50				0.00	0.00	LHS
34	03/06/08	7.998	8.031	33.00	3.50		115.50				0.00	0.00	LHS
35	03/06/08	8.031	8.038	7.00	3.50		24.50				0.00	0.00	LHS
36	03/06/08	8.038	8.138	100.00	3.70		370.00				0.00	0.00	LHS
37	03/06/08	8.138	8.145	7.00	3.70		25.90				0.00	0.00	LHS
38	03/06/08	8.145	8.188	43.00	4.00		172.00				0.00	0.00	LHS
39	03/06/08	8.188	8.211	23.00	4.00		92.00				0.00	0.00	LHS
40	03/06/08	8.211	8.247	36.00	3.70		133.20				0.00	0.00	LHS
41	03/06/08	8.247	8.255	8.00	3.70		29.60				0.00	0.00	LHS
42	03/06/08	8.255	8.308	53.00	5.30		280.90				0.00	0.00	LHS
43	03/06/08	8.308	8.314	6.00	5.30		31.80				0.00	0.00	LHS
44	03/06/08	8.314	8.362	48.00	5.80		278.40				0.00	0.00	LHS
45	03/06/08	8.362	8.369	7.00	5.80		40.60				0.00	0.00	LHS
46	03/06/08	8.369	8.452	83.00	6.00		498.00				0.00	0.00	LHS
47	03/06/08	8.452	8.458	6.00	6.00		36.00				0.00	0.00	LHS
48	03/06/08	8.458	8.535	77.00	4.40		338.80				0.00	0.00	LHS
49	03/06/08	8.535	8.602	67.00	2.50		167.50				0.00	0.00	LHS
50	03/06/08	8.602	8.609	7.00	2.50		17.50				0.00	0.00	LHS
51	04/06/08	8.609	8.716	107.00	6.00		642.00				0.00	0.00	LHS
52	04/06/08	8.716	8.723	7.00	6.00		42.00				0.00	0.00	LHS
53	04/06/08	8.723	8.753	30.00	3.80		114.00				0.00	0.00	LHS
54	04/06/08	8.753	8.760	7.00	3.80		26.60				0.00	0.00	LHS
55	04/06/08	8.760	8.781	21.00	3.60		75.60				0.00	0.00	LHS
56	04/06/08	8.838	8.858	20.00	4.00		80.00				0.00	0.00	LHS
57	04/06/08	8.858	8.865	7.00	4.00		28.00				0.00	0.00	LHS
58	04/06/08	8.865	8.955	90.00	4.30		387.00				0.00	0.00	LHS
59	04/06/08	8.955	8.960	5.00	4.30		21.50				0.00	0.00	LHS
60	04/06/08	8.960	9.013	53.00	4.60		243.80				0.00	0.00	LHS
61	04/06/08	9.037	9.075	38.00	2.70		102.60				0.00	0.00	LHS
<b>TOTAL:</b>							<b>18,883.60</b>				<b>890.08</b>	<b>106.75</b>	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** PAPAR

**ROUTE NO.:** 01

**ROAD NAME:** JALAN KK-SINDUMIN

**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
							60.00				38.11	6.86	
<b>TOTAL:</b>							60.00				38.11	6.86	

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

**SUMMARY- SHOULDER REPAIR RECORD**

MONTH : JUNE 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	115.00	83.00	198.00	-	-	-	-	-	-
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	67.00	-	67.00	-	-	-	-	-	-
3	Kudat	01	Jalan Kota Kinabalu - Kudat	125.00	35.00	160.00	-	-	-	-	-	-
<b>TOTAL</b>				<b>307.00</b>	<b>118.00</b>	<b>425.00</b>	-	-	-	-	-	-

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

DISTRICT: KOTA BELUD  
 ROUTE NO. 01  
 ROAD NAME: JALAN KOTA KINABALU- KUDAT  
 MONTH: JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER				REMARKS	
				Length	Width	Depth	Area	Length	Width	Depth	Area		Volume
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )		(m <sup>3</sup> )
		<b>BROUGHT FORWARD:</b>					<b>115.00</b>						
1	12/06/2008	106.660	106.693	33.00	1.00	0.100	33.00						
2	18/06/2008	102.125	102.175	50.00	1.00	0.100	50.00						
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>BALANCE END OF JUNE :</b>							<b>198.00</b>				<b>0.00</b>	<b>0.00</b>	

**LINTASAN RESOURCES SDN. BHD.**  
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KOTA MARUDU  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
<b>BROUGHT FORWARD:</b>				-	-	-	67.00	-	-	-			
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>BALANCE END OF JUNE :</b>							67.00				0.00	0.00	

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** KUDAT  
**ROUTE NO.** 01  
**ROAD NAME:** JALAN KOTA KINABALU - KUDAT  
**MONTH:** JUNE 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER				REMARKS	
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area		Volume
				(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)		(m3)
		<b>BROUGHT FORWARD:</b>		-	-	-	<b>125.00</b>	-	-	-			
1	06/06/2008	175.320	195.355	35.00	1.00	0.100	35.00						
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>BALANCE END OF JUNE :</b>							<b>160.00</b>				<b>0.00</b>	<b>0.00</b>	

**LINTASAN RESOURCES SDN. BHD.**  
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

***SUMMARY- SHOULDER REPAIR RECORD***

***MONTH : JUNE 2008***

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM MONTH	
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )
1	Ranau	22	Jalan Kota Kinabalu - Sandakan	1,666.00	599.80	2,265.80	-	-	-	-	-	-
<b>TOTAL</b>				<b>1,666.00</b>	<b>599.80</b>	<b>2,265.80</b>	-	-	-	-	-	-

**LINTASAN RESOURCES SDN. BHD.**  
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH  
**R02 SHOULDER REPAIR RECORD**

**DISTRICT:** Ranau  
**ROUTE NO.** 22  
**ROAD NAME:** Jalan Kota Kinabalu - Sandakan  
**MONTH:** June 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m <sup>2</sup> )	(m)	(m)	(m)	(m <sup>2</sup> )	(m <sup>3</sup> )	
<b>BROUGHT FORWARD FROM MAY 2008:</b>						<b>1,666.00</b>				<b>0.00</b>	<b>0.00</b>		
1	05/06/08	63.000	63.062	62.00	1.80		111.60					RHS	
2	06/06/08	63.100	63.168	68.00	3.80		258.40					RHS	
3	11/06/08	61.200	61.261	61.00	1.50		91.50					RHS	
4	12/06/08	61.200	61.261	61.00	1.50		91.50					LHS	
5	17/06/08	62.500	62.536	36.00	1.30		46.80					RHS	
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
<b>CARRIED FORWARD:</b>							<b>2,265.80</b>			<b>0.00</b>	<b>0.00</b>		

LINTASAN RESOURCES SDN. BHD.  
 MAINTENANCE OF FEDERAL ROADS - LABUAN, FT

**SUMMARY- SHOULDER REPAIR RECORD**

Month : JUNE 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER						
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM MONTH		
				Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	Area (m <sup>2</sup> )	Volume (m <sup>3</sup> )	
1	W.P LABUAN	L 700	JALAN PATAU	10,894.00	-	10,894.00	-	-	-	-	-	-	-
2	W.P LABUAN	L 700	JALAN POHON	-	-	-	-	-	-	-	-	-	-
3	W.P LABUAN	L 700	JALAN TUN M	-	-	-	-	-	-	-	-	-	-
4	W.P LABUAN	L 704	JALAN MOHD	-	-	-	-	-	-	-	-	-	-
5	W.P LABUAN	L 706	JALAN RANCI	100.00	750.00	850.00	-	-	-	-	-	-	-
6	W.P LABUAN	L 710	JALAN BUKIT	-	47.10	47.10	165.50	49.65	-	-	165.50	49.65	-
7	W.P LABUAN	L 719	JALAN PENGH	-	-	-	-	-	-	-	-	-	-
8	W.P LABUAN	L 722	JALAN RANCI	-	-	-	-	-	-	-	-	-	-
9	W.P LABUAN	L 731	JALAN ARSAI	800.00	-	800.00	-	-	-	-	-	-	-
10	W.P LABUAN	L 734	JALAN PANCU	850.00	-	850.00	-	-	-	-	-	-	-
<b>TOTAL</b>				<b>12,644.00</b>	<b>797.10</b>	<b>13,441.10</b>	<b>165.50</b>	<b>49.65</b>	<b>-</b>	<b>-</b>	<b>165.50</b>	<b>49.65</b>	

LINTASAN RESOURCES SDN. BHD.  
 MAINTENANCE OF FEDERAL ROADS - LABUAN, FT  
**R02 SHOULDER REPAIR RECORD**

DISTRICT: W.P LABUAN  
 ROUTE NO. L 710  
 ROAD NAME: JALAN BUKIT KUDA  
 MONTH: JUNE 2008

ITEM	DATE	CHAINAGE (KM)		EARTH SHOULDER				GRAVEL SHOULDER				REMARKS	
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)		Volume (m3)
BROUGHT FORWARD MAY 08:													
1	18/06/2008	2650	2665	15.00	2.50	0.15	37.50	-	-	-	165.50	49.65	RHS
2	"	2650	2658	8.00	1.20	0.15	9.60						LHS
<b>TOTAL:</b>							<b>47.10</b>				<b>165.50</b>	<b>49.65</b>	

LINTASAN RESOURCES SDN. BHD.  
 MAINTENANCE OF FEDERAL ROADS - LABUAN, FT  
**R02 SHOULDER REPAIR RECORD**

DISTRICT: W.P LABUAN  
 ROUTE NO. L 706  
 ROAD NAME: JALAN RANCHA-RANCHA  
 MONTH: JUNE 2008

ITEM	DATE	CHAINAGE (KM)		EARTH SHOULDER				GRAVEL SHOULDER				REMARKS	
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)		Volume (m3)
BROUGHT FORWARD MAY 1	30/06/2008	2600	2900	300.00	2.50	0.15	100.00 750.00	-	-	-	0.00	0.00	RHS
<b>TOTAL :</b>							850.00				0.00	0.00	