

RO2

(SHOULDER)

DISTRICT : BEAUFORT
ROUTE NO : 01 JALAN KOTA KINABALU - SINDUMIN
LOCATION : CH93.140 (KM94.900) - RHS

R02 SHOULDER REPAIR



BEFORE



IN PROGRESS



AFTER

LINTASAN RESOURCES SDN BHD
PRIVATISATION OF LABUAN FEDERAL ROADS MAINTENANCE

R02 ~ ROAD SHOULDER.

Road Name : Jalan Penghulu Tuah

Route No : L719

Location : KM 1.50 RHS

Date : 18-Sep-08

BEFORE



Film Batch: L9-15-190

IN PROGRESS



Film Batch: L9-15-194

AFTER



Film Batch: L9-17-072

SHOULDER REPAIR GRAND SUMMARY

MONTH: SEPTEMBER 2008

DISTRICT	ROUTE NO	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
			Previous	Current	Cumm.	Previous		Current		Cumm.	
			Area (m ²)	Area (m ²)	Area (m ²)	Area (m ²)	Vol (m ³)	Area (m ²)	Vol (m ³)	Area (m ²)	Vol (m ³)
Kota Belud	01	Jalan Kota Kinabalu-Kudat	295.00	140.00	435.00	0.00	0.00	0.00	0.00	0.00	0.00
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	267.00	0.00	267.00	0.00	0.00	0.00	0.00	0.00	0.00
Kudat	01	Jalan Kota Kinabalu-Kudat	160.00	20.00	180.00	0.00	0.00	0.00	0.00	0.00	0.00
Tuaran	01	Jalan Kota Kinabalu-Kudat	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	22	Jalan Kota Kinabalu-Sandakan	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	503	Jalan Berungis-Kota Belud	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	0.00	0.00	0.00	62.16	15.42	0.00	0.00	62.16	15.42
	01	Jalan Kota Kinabalu-Sindumin	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	606	Jalan Susur Sepangar Bay	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	607	Jalan Masuk Ke Pelabuhan Baru	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	608	Jalan Masuk ke Lapangan Terbang Lama	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Penampang	01	Jalan Kota Kinabalu-Sindumin	18,883.60	0.00	18,883.60	890.08	106.75	0.00	0.00	890.08	106.75
	500	Jalan Kota Kinabalu-Keningau-Tenom	1,568.02	300.00	1,868.02	0.00	0.00	0.00	0.00	0.00	0.00
	501	Jalan Kota Kinabalu-Penampang-Lokkawi	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Papar	01	Jalan Kota Kinabalu-Sindumin	60.00	258.00	318.00	38.11	6.86	0.00	0.00	38.11	6.86
Ranau	22	Jalan Kota Kinabalu-Sandakan	4,822.30	0.00	4,822.30	0.00	0.00	0.00	0.00	0.00	0.00
Tambunan	500	Jalan Kota Kinabalu-Keningau-Tenom	2,856.80	556.70	3,413.50	123.00	20.12	0.00	0.00	123.00	20.12
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	65.60	53.20	118.80	27.50	3.46	0.00	0.00	27.50	3.46
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	22.20	0.00	22.20	0.00	0.00	0.00	0.00	0.00	0.00
Beaufort	01	Jalan Kota Kinabalu-Sindumin	2,685.65	0.00	2,685.65	0.00	0.00	37.00	2.90	37.00	2.90
	502	Jalan Beaufort-Menumbok	91.60	0.00	91.60	0.00	0.00	0.00	0.00	0.00	0.00
Sipitang	01	Jalan Kota Kinabalu-Sindumin	36.20	0.00	36.20	35.60	3.12	0.00	0.00	35.60	3.12
Kuala Penyu	502	Jalan Beaufort-Menumbok	35.40	0.00	35.40	0.00	0.00	0.00	0.00	0.00	0.00
TOTAL			31,849.37	1,327.90	33,177.27	1,176.45	155.73	37.00	2.90	1,213.45	158.63

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

Month : SEPTEMBER 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m ²)	Area (m ²)	Area (m ²)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	2,685.65	-	2,685.65	-	-	37.00	2.90	37.00	2.90
2	Beaufort	502	Jalan Beaufort - Menumbok	91.60	-	91.60	-	-	-	-	-	-
3	Sipitang	01	Jalan Kota Kinabalu - Sindumin	36.20	-	36.20	35.60	3.12	-	-	35.60	3.12
4	Kuala Penyu	502	Jalan Beaufort - Menumbok	35.40	-	35.40	-	-	-	-	-	-
TOTAL				2,848.85	-	2,848.85	35.60	3.12	37.00	2.90	72.60	6.02

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: BEAUFORT
ROUTE NO. 01
ROAD NAME: JALAN KOTA KINABALU - SINDUMIN
MONTH: SEPT 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m ²)	(m)	(m)	(m)	(m ²)	(m ³)	
BROUGHT FORWARD:				-	-	-	2,685.65	-	-	-	0.00	0.00	-
1	8-Sep-08	93.130	93.135					5.00	2.00	0.080	10.00	0.80	RHS
2	8-Sep-08	93.132	93.134					2.00	0.50	0.075	1.00	0.07	RHS
3	8-Sep-08	93.136	93.139					3.00	2.80	0.075	8.40	0.63	RHS
4	8-Sep-08	93.140	93.148					8.00	1.00	0.080	8.00	0.64	RHS
5	8-Sep-08	93.141	93.144					3.00	2.00	0.080	6.00	0.48	RHS
6	8-Sep-08	93.147	93.150					3.00	1.00	0.075	3.00	0.23	RHS
7	8-Sep-08	93.150	93.151					1.00	0.60	0.090	0.60	0.05	RHS
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
CARRIED FORWARD:							2,685.65				37.00	2.90	

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY - SHOULDER REPAIR RECORD

Month : SEPTEMBER 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER					
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH	
				Area (m ²)	Area (m ²)	Area (m ²)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)
1	TAMBUNAN	500	Jalan Kota Kinabalu - Keningau - Tenom	2,856.80	556.70	3,413.50	123.30	20.12	-	-	123.30	20.12
2	KENINGAU	500	Jalan Kota Kinabalu - Keningau - Tenom	65.60	53.20	118.80	27.50	3.46	-	-	27.50	3.46
3	TENOM	500	Jalan Kota Kinabalu - Keningau - Tenom	22.20	-	22.20	-	-	-	-	-	-
TOTAL				2,944.60	609.90	3,554.50	150.80	23.58	-	-	150.80	23.58

LINTASAN RESOURCES SDN. BHD.

MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: TAMBUNAN

ROUTE NO. 500

ROAD NAME: JLN K. KINABALU - KENINGAU - TENOM

MONTH: September 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
BROUGHT FORWARD:							2,856.80				123.30	20.12	
1	02 Sep 08	60.950	60.984	34.00	2.00	0.150	68.00						Drop Off/LHS
2	02 Sep 08	48.867	48.874	7.00	1.20	0.150	8.40						Drop Off/LHS
3	02 Sep 08	49.010	49.011	1.00	1.20	0.075	1.20						Drop Off/LHS
4	02 Sep 08	49.020	49.027	7.00	2.00	0.075	14.00						Drop Off/LHS
5	02 Sep 08	49.000	49.002	2.00	1.50	0.100	3.00						Drop Off/RHS
6	02 Sep 08	48.975	48.977	2.00	1.30	0.100	2.60						Drop Off/RHS
7	02 Sep 08	48.968	48.970	2.00	1.90	0.100	3.80						Drop Off/RHS
8	02 Sep 08	48.957	48.959	2.00	1.40	0.100	2.80						Drop Off/RHS
9	02 Sep 08	48.950	48.951	1.00	1.30	0.100	1.30						Drop Off/RHS
10	02 Sep 08	48.942	48.946	4.00	2.40	0.100	9.60						Drop Off/RHS
11	02 Sep 08	48.570	48.645	75.00	1.50	0.125	112.50						Drop Off/RHS
12	02 Sep 08	48.100	48.140	40.00	1.00	0.100	40.00						Drop Off/RHS
13	02 Sep 08	47.921	47.956	35.00	1.40	0.125	49.00						Drop Off/RHS
14	02 Sep 08	47.940	47.958	18.00	1.00	0.100	18.00						Drop Off/LHS
15	02 Sep 08	47.387	47.400	13.00	0.90	0.100	11.70						Drop Off/LHS
16	03 Sep 08	45.600	45.675	75.00	1.50	0.100	112.50						Drop Off/RHS
17	03 Sep 08	45.240	45.258	18.00	0.80	0.100	14.40						Drop Off/LHS
18	03 Sep 08	45.138	45.160	22.00	1.00	0.125	22.00						Drop Off/LHS
19	03 Sep 08	56.178	56.205	27.00	1.00	0.100	27.00						Drop Off/RHS
20	09 Sep 08	45.350	45.364	14.00	1.00	0.250	14.00						Drop Off/LHS
21	26 Sep 08	69.559	69.563	4.00	1.70	0.150	6.80						Ponding/RHS
22	26 Sep 08	69.557	69.559	2.00	1.00	0.050	2.00						Ponding/RHS
23	26 Sep 08	69.547	69.548	1.00	0.70	0.050	0.70						Ponding/RHS
24	26 Sep 08	69.537	69.541	4.00	1.80	0.200	7.20						Ponding/RHS
25	26 Sep 08	69.554	69.557	3.00	1.00	0.100	3.00						Ponding/RHS
26	26 Sep 08	69.553	69.554	1.00	1.20	0.050	1.20						Ponding/RHS
27													
28													
29													
30													
TOTAL							3,413.50				123.30	20.12	

LINTASAN RESOURCES SDN. BHD.

MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: KENINGAU

ROUTE NO. 500

ROAD NAME: JLN K. KINABALU - KENINGAU - TENOM

MONTH: September 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS	
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume		
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)		
BROUGHT FORWARD:							65.60					27.50	3.46	
1	15 Sep 08	115.673	115.676	3.00	2.20	0.150	6.60							Ponding/RHS
2	15 Sep 08	115.672	115.675	3.00	2.20	0.200	6.60							Ponding/RHS
3	15 Sep 08	115.670	115.673	3.00	2.00	0.200	6.00							Ponding/RHS
4	15 Sep 08	115.658	115.661	3.00	2.70	0.300	8.10							Ponding/RHS
5	15 Sep 08	115.650	115.653	3.00	2.30	0.250	6.90							Ponding/RHS
6	15 Sep 08	115.600	115.602	2.00	1.70	0.125	3.40							Ponding/RHS
7	16 Sep 08	116.925	116.928	3.00	1.20	0.300	3.60							Drop off/RHS
8	16 Sep 08	116.920	116.922	2.00	1.50	0.300	3.00							Drop off/RHS
9	16 Sep 08	116.030	116.033	3.00	1.80	0.200	5.40							Drop off/RHS
10	16 Sep 08	116.025	116.027	2.00	1.80	0.200	3.60							Drop off/RHS
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
TOTAL							118.80					27.50	3.46	

LINTASAN RESOURCES SDN. BHD.
 PRIVATISATION OF WEST COAST SABAH FEDERAL ROADS MAINTENANCE

SUMMARY- SHOULDER REPAIR RECORD

Month: September 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER						
				PREVIOUS MONTH	CURRENT MONTH	CUM MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM MONTH		
				Area (m ²)	Area (m ²)	Area (m ²)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)	
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-	-	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	18,883.60	-	18,883.60	890.08	106.75	-	-	890.08	106.75	-
3	Papar	01	Jalan Kota Kinabalu - Sindumin	60.00	258.00	318.00	38.11	6.86	-	-	38.11	6.86	-
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	1,568.02	300.00	1,868.02	-	-	-	-	-	-	-
5	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	-	-	-	-	-	-	-	-	-	-
6	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	-	-	-	-	-	-	-	-	-	-
TOTAL				20,511.62	558.00	21,069.62	928.19	113.61	-	-	928.19	113.61	-

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PENAMPANG

ROUTE NO.: 500

ROAD NAME: JALAN KK-KENINGAU-TENOM

MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m ²)	Length (m)	Width (m)	Depth (m)	Area (m ²)	Volume (m ³)	
1	06 Sep 08	8.280	8.400	120.00	2.50		300.00				0.00	0.00	RHS
BROUGHT FORWARD:							1,568.02				0.00	0.00	
TOTAL:							1,868.02				0.00	0.00	

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PAPAR

ROUTE NO.: 01

ROAD NAME: JALAN KK-SINDUMIN

MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
BROUGHT FORWARD:							60.00				38.11	6.86	
1	01 Sep 08	16.935	16.938	3.00	2.00		6.00						RHS
2	01 Sep 08	17.235	17.238	3.00	2.00		6.00						RHS
3	01 Sep 08	18.335	18.338	3.00	2.00		6.00						RHS
4	01 Sep 08	18.735	18.738	3.00	2.00		6.00						RHS
5	01 Sep 08	19.385	19.388	3.00	2.00		6.00						RHS
6	01 Sep 08	20.055	20.058	3.00	2.00		6.00						RHS
7	02 Sep 08	20.457	20.460	3.00	2.00		6.00						RHS
8	02 Sep 08	22.035	22.038	3.00	2.00		6.00						RHS
9	02 Sep 08	23.350	23.353	3.00	2.00		6.00						RHS
10	02 Sep 08	24.035	24.038	3.00	2.00		6.00						RHS
11	02 Sep 08	24.835	24.838	3.00	2.00		6.00						LHS
12	02 Sep 08	25.185	25.188	3.00	2.00		6.00						RHS
13	02 Sep 08	25.827	25.830	3.00	2.00		6.00						RHS
14	04 Sep 08	25.935	25.938	3.00	2.00		6.00						RHS
15	04 Sep 08	26.145	26.148	3.00	2.00		6.00						RHS
16	04 Sep 08	26.823	26.826	3.00	2.00		6.00						RHS
17	04 Sep 08	27.265	27.268	3.00	2.00		6.00						RHS
18	04 Sep 08	27.505	27.508	3.00	2.00		6.00						LHS
19	04 Sep 08	29.719	29.722	3.00	2.00		6.00						RHS
20	04 Sep 08	30.167	30.172	5.00	2.00		10.00						RHS
21	14 Sep 08	30.247	30.257	10.00	2.00		20.00						RHS
22	14 Sep 08	34.190	34.193	3.00	2.00		6.00						RHS
23	14 Sep 08	34.535	34.538	3.00	2.00		6.00						LHS
24	14 Sep 08	34.835	34.838	3.00	2.00		6.00						LHS
25	14 Sep 08	36.413	36.416	3.00	2.00		6.00						RHS
26	14 Sep 08	36.735	36.738	3.00	2.00		6.00						RHS
27	15 Sep 08	37.535	37.538	3.00	2.00		6.00						RHS
28	15 Sep 08	37.635	37.638	3.00	2.00		6.00						RHS
29	15 Sep 08	38.205	38.208	3.00	2.00		6.00						RHS
30	15 Sep 08	39.035	39.038	3.00	2.00		6.00						RHS
CARRIED FORWARD:							258.00				38.11	6.86	

LINTASAN RESOURCES SDN. BHD.
MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH
R02 SHOULDER REPAIR RECORD

DISTRICT: PAPAR

ROUTE NO.: 01

ROAD NAME: JALAN KK-SINDUMIN

MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length (m)	Width (m)	Depth (m)	Area (m2)	Length (m)	Width (m)	Depth (m)	Area (m2)	Volume (m3)	
BROUGHT FORWARD:							258.00				38.11	6.86	
31	15 Sep 08	39.085	39.088	3.00	2.00		6.00						RHS
32	15 Sep 08	39.305	39.308	3.00	2.00		6.00						RHS
33	15 Sep 08	39.175	39.178	3.00	2.00		6.00						RHS
34	16 Sep 08	39.685	39.688	3.00	2.00		6.00						RHS
35	16 Sep 08	39.935	39.938	3.00	2.00		6.00						RHS
36	16 Sep 08	40.635	40.638	3.00	2.00		6.00						RHS
37	16 Sep 08	41.395	41.398	3.00	2.00		6.00						RHS
38	16 Sep 08	42.235	42.238	3.00	2.00		6.00						RHS
39	16 Sep 08	42.635	42.638	3.00	2.00		6.00						RHS
40	16 Sep 08	43.735	43.738	3.00	2.00		6.00						RHS
TOTAL:							318.00				38.11	6.86	

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: KOTA BELUD
ROUTE NO. 01
ROAD NAME: JALAN KOTA KINABALU- KUDAT
MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
BROUGHT FORWARD:							295.00						
1	09 Sep 08	108.020	108.060	2.00	40.00	0.100	80.00						
2	18 Sep 08	101.52	101.550	2.00	30.00	0.100	60.00						
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
BALANCE END OF SEPT :							435.00				0.00	0.00	

LINTASAN RESOURCES SDN. BHD.

MAINTENANCE OF FEDERAL ROADS - WEST COAST, SABAH

R02 SHOULDER REPAIR RECORD

DISTRICT: KUDAT

ROUTE NO. 01

ROAD NAME: JALAN KOTA KINABALU - KUDAT

MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
				Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
		From	To	(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
BROUGHT FORWARD:				-	-	-	160.00	-	-	-			
1	03 Sep 08	187.300	187.320	1.00	20.00	0.100	20.00						
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													
16													
17													
18													
19													
20													
21													
22													
23													
24													
25													
26													
27													
28													
29													
30													
BALANCE END OF SEPT :							180.00				0.00	0.00	

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - LABUAN, FT

SUMMARY- SHOULDER REPAIR RECORD

Month : SEPTEMBER 2008

ITEM	DISTRICT	ROUTE NO.	ROAD NAME	EARTH SHOULDER			GRAVEL SHOULDER						
				PREVIOUS MONTH	CURRENT MONTH	CUM. MONTH	PREVIOUS MONTH		CURRENT MONTH		CUM. MONTH		
				Area (m ²)	Area (m ²)	Area (m ²)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)	Area (m ²)	Volume (m ³)	
1	W.P LABUAN	L 700	JALAN PATAU-PATAU	11,106.80	-	11,106.80	-	-	-	-	-	-	-
2	W.P LABUAN	L 700	JALAN POHON BATU	-	-	-	-	-	-	-	-	-	-
3	W.P LABUAN	L 700	JALAN TUN MUSTAPHA	-	-	-	-	-	-	-	-	-	-
4	W.P LABUAN	L 703	JALAN OKK DAUD	1,350.00	-	1,350.00	-	-	-	-	-	-	-
5	W.P LABUAN	L 704	JALAN MOHD SALLEH	257.90	-	257.90	-	-	-	-	-	-	-
6	W.P LABUAN	L 706	JALAN RANCHA-RANCHA	850.00	-	850.00	-	-	-	-	-	-	-
7	W.P LABUAN	L 710	JALAN BUKIT KUDA	361.35	2,098.00	2,459.35	165.50	49.65	-	-	165.50	49.65	-
8	W.P LABUAN	L 719	JALAN PENGHULU TUAH	-	1,389.40	1,389.40	-	-	-	-	-	-	-
9	W.P LABUAN	L 722	JALAN RANCHA-RANCHA LAMA	-	-	-	-	-	-	-	-	-	-
10	W.P LABUAN	L 731	JALAN ARSAT	800.00	-	800.00	-	-	-	-	-	-	-
11	W.P LABUAN	L 734	JALAN PANCUR HITAM	898.06	-	898.06	-	-	-	-	-	-	-
TOTAL				15,624.11	3,487.40	19,111.51	165.50	49.65	-	-	165.50	49.65	

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - LABUAN, FT
R02 SHOULDER REPAIR RECORD

DISTRICT: W.P LABUAN
 ROUTE NO. L 719
 ROAD NAME: JALAN PENGHULU TUAH
 MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE (KM)		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
BROUGHT FORWARD AUG 08:				-	-	-	0.00	-	-	-	0.00	0.00	
1	18-Sep-08	1.53	1.61	83.00	1.50	0.15	124.50						LHS
2	"	1.35	1.39	42.00	4.00	0.15	168.00						LHS
3	"	1.40	1.43	25.00	4.00	0.15	100.00						LHS
4	"	1.22	1.31	87.00	3.20	0.15	278.40						LHS
5	19-Sep-08	1.22	1.31	87.00	3.00	0.15	261.00						RHS
6	"	1.43	1.61	183.00	2.50	0.15	457.50						RHS
TOTAL :							1,389.40				0.00	0.00	

LINTASAN RESOURCES SDN. BHD.
 MAINTENANCE OF FEDERAL ROADS - LABUAN, FT
R02 SHOULDER REPAIR RECORD

DISTRICT: W.P LABUAN
 ROUTE NO. L 710
 ROAD NAME: JALAN BUKIT KUDA
 MONTH: SEPTEMBER 2008

ITEM	DATE	CHAINAGE (KM)		EARTH SHOULDER				GRAVEL SHOULDER					REMARKS
		From	To	Length	Width	Depth	Area	Length	Width	Depth	Area	Volume	
				(m)	(m)	(m)	(m2)	(m)	(m)	(m)	(m2)	(m3)	
BROUGHT FORWARD AUG 08:				-	-	-	361.35	-	-	-	0.00	0.00	
1	20-Sep-08	1.85	2.43	587.00	2.00	0.15	1,174.00						LHS/RHS
2	"	2.41	2.66	250.00	2.00	0.15	500.00						LHS/RHS
3	"	2.95	3.16	212.00	2.00	0.15	424.00						LHS/RHS
TOTAL :							2,459.35				0.00	0.00	