

# R07

(DRAINAGE)

LINTASAN RESOURCES SDN. BHD.  
**DRAINAGE CLEARING**  
**GRAND SUMMARY**

MONTH: JANUARY 2006

DISTRICT	ROUTE NO.	ROAD NAME	Earth Drain			Lined Drain		
			Previous	Current	Cumm.	Previous	Current	Cumm.
			(m)	(m)	(m)	(m)	(m)	(m)
Kota Belud	01	Jalan Kota Kinabalu-Kudat	0	4,900	4,900	0	4,015	4,015
Kota Marudu	01	Jalan Kota Kinabalu-Kudat	0	3,092	3,092	0	0	0
Kudat	01	Jalan Kota Kinabalu-Kudat	0	9,852	9,852	0	663	663
Tuaran	01	Jalan Kota Kinabalu-Kudat	0	726	726	0	14,609	14,609
	22	Jalan Kota Kinabalu-Sandakan	0	0	0	0	0	0
	503	Jalan Berungis-Kota Belud	0	0	0	0	1,629	1,629
Kota Kinabalu	01	Jalan Kota Kinabalu-Kudat	0	14,947	14,947	0	40,055	40,055
	01	Jalan Kota Kinabalu-Sindumin	0	0	0	0	0	0
	606	Jalan Susur Sepangar Bay	0	0	0	0	0	0
	607	Jalan Masuk Ke Pelabuhan Baru	0	0	0	0	0	0
	608	Jalan Masuk Ke Lapangan Terbang Lama	0	0	0	0	0	0
Penampang	01	Jalan Kota Kinabalu-Sindumin	0	9,345	9,345	0	12,598	12,598
	500	Jalan Kota Kinabalu-Keningau-Tenom	0	0	0	0	0	0
	501	Jalan Kota Kinabalu-Penampang-Lok Kawi	0	252	252	0	5,302	5,302
Papar	01	Jalan Kota Kinabalu-Sindumin	0	0	0	0	0	0
Ranau	22	Jalan Kota Kinabalu-Sandakan	0	5,743	5,743	0	11,978	11,978
Tambunam	500	Jalan Kota Kinabalu-Keningau-Tenom	0	6,739	6,739	0	24,958	24,958
Keningau	500	Jalan Kota Kinabalu-Keningau-Tenom	0	0	0	0	0	0
Tenom	500	Jalan Kota Kinabalu-Keningau-Tenom	0	0	0	0	0	0
Beaufort	01	Jalan Kota Kinabalu-Sindumin	0	0	0	0	0	0
	502	Jalan Beaufort-Menumbok	0	29,590	29,590	0	0	0
Sipitang	01	Jalan Kota Kinabalu-Sindumin	0	0	0	0	0	0
Kuala Penyu	502	Jalan Beaufort-Menumbok	0	4,620	4,620	0	0	0
<b>TO TAL</b>			<b>0</b>	<b>89,806</b>	<b>89,806</b>	<b>0</b>	<b>115,807</b>	<b>115,807</b>

**LINTASAN RESOURCES SDN. BHD.**

*INDONESIA DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - DRAINAGE CLEARING**

Month : January 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Earth Drain			Lined Drain		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(m)	(m)	(m)	(m)	(m)	(m)
1	Kota Belud	01	Jalan Kota Kinabalu - Kudat	-	4,900	4,900	-	4,015	4,015
2	Kota Marudu	01	Jalan Kota Kinabalu - Kudat	-	3,092	3,092	-	-	-
3	Kudat	01	Jalan Kota Kinabalu - Kudat	-	9,852	9,852	-	663	663
<b>TOTAL :</b>				-	<b>17,844</b>	<b>17,844</b>	-	<b>4,678</b>	<b>4,678</b>

**LINTASAN RESOURCES SDN. BHD.**

*INCORPORATED IN WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - DRAINAGE CLEARING**

Month : January 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Earth Drain			Lined Drain		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(m)	(m)	(m)	(m)	(m)	(m)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Kudat	-	14,947	14,947	-	40,055	40,055
2	Tuaran	01	Jalan Kota Kinabalu - Kudat	-	726	726	-	14,609	14,609
3	Tuaran	22	Jalan Kota Kinabalu - Sandakan	-	-	-	-	-	-
4	Tuaran	503	Jalan Berungis - Kota Belud	-	-	-	-	1,629	1,629
5	Kota Kinabalu	606	Jalan Susur Sepangar Bay	-	-	-	-	-	-
6	Kota Kinabalu	607	Jalan Masuk Ke Pelabuhan Baru, KK	-	-	-	-	-	-
<b>TOTAL :</b>				-	<b>15,673</b>	<b>15,673</b>	-	<b>56,293</b>	<b>56,293</b>

**LINTASAN RESOURCES SDN. BHD.**

*INDONESIA DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - DRAINAGE CLEARING**

*Month : January 2006*

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Earth Drain			Lined Drain		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(m)	(m)	(m)	(m)	(m)	(m)
1	Ranau	22	Jalan Kota Kinabalu - Sandakan	-	5,743	5,743	-	11,978	11,978
			<b>TOTAL :</b>	-	5,743	5,743	-	11,978	11,978

**LINTASAN RESOURCES SDN. BHD.**

*INDONESIA DIVISION OF WEST COAST SUB-FEDERAL ROADS MAINTENANCE*

**SUMMARY - DRAINAGE CLEARING**

Month : January 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Earth Drain			Lined Drain		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(m)	(m)	(m)	(m)	(m)	(m)
1	Kota Kinabalu	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-
2	Penampang	01	Jalan Kota Kinabalu - Sindumin	-	9,345	9,345	-	12,598	12,598
3	Papar	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-
4	Penampang	500	Jalan Kota Kinabalu - Keningau - Tenom	-	-	-	-	-	-
5	Penampang	501	Jalan Kota Kinabalu - Penampang - Lok Kawi	-	252	252	-	5,302	5,302
6	Kota Kinabalu	608	Jalan Masuk Ke Lapangan Terbang Lama, KK	-	-	-	-	-	-
<b>TOTAL :</b>				-	<b>9,597</b>	<b>9,597</b>	-	<b>17,900</b>	<b>17,900</b>

**LINTASAN RESOURCES SDN. BHD.**

*INCORPORATED IN WEST COAST SUB-FEDERAL ROAD MAINTENANCE*

**SUMMARY - DRAINAGE CLEARING**

Month : January 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Earth Drain			Lined Drain		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(m)	(m)	(m)	(m)	(m)	(m)
1	Tambunan	500	Jalan Kota Kinabalu - Keningau - Tenom	-	6,739	6,739	-	24,958	24,958
2	Keningau	500	Jalan Kota Kinabalu - Keningau - Tenom	-	-	-	-	-	-
3	Tenom	500	Jalan Kota Kinabalu - Keningau - Tenom	-	-	-	-	-	-
<b>TOTAL :</b>				-	<b>6,739</b>	<b>6,739</b>	-	<b>24,958</b>	<b>24,958</b>

**LINTASAN RESOURCES SDN. BHD.**

*INCORPORATED IN WEST COAST SUB-FEDERAL ROAD MAINTENANCE*

**SUMMARY - DRAINAGE CLEARING**

Month : January 2006

ITEM	DISTRICT	ROUTE NO	ROAD NAME	Earth Drain			Lined Drain		
				Previous	Current	Cumm.	Previous	Current	Cumm.
				(m)	(m)	(m)	(m)	(m)	(m)
1	Beaufort	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-
2	Sipitang	01	Jalan Kota Kinabalu - Sindumin	-	-	-	-	-	-
3	Beaufort	502	Jalan Beaufort - Menumbok	-	29,590	29,590	-	-	-
4	Kuala Penyu	502	Jalan Beaufort - Menumbok	-	4,620	4,620	-	-	-
<b>TOTAL :</b>				-	<b>34,210</b>	<b>34,210</b>	-	-	-